

Recall Detail

| | |
|---|---|
| Ref No | 10000496 |
| Manufacturer | Infiniti |
| Vehicle Class | Private Car |
| Model/Type | Q50S (V37) |
| Dealer (phone no) | Honest Motors Ltd. (Tel: 22168228) |
| Subject | Reprogramming of Traction Motor Inverter |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | The traction motor inverter of hybrid system may incorrectly diagnose as a trouble in the communication condition diagnosis between the inverter and TCM (Transmission Control Module) during the driving. As a result, the inverter system will be suppressed and the warning lamps will be turned on. If the vehicle is in the driving by only the traction motor, the vehicle may stop. |
| Remedial Action | Reprogram Traction Motor Inverter |
| Build Dates | Q50S (V37): 24-FEB-2014 to 03-JUN-2014 |
| Launch Date | 30/09/2014 |
| Tentative Date of Recall Completion | 30/09/2015 |

Q50S (V37)

| | | | |
|----|-------------------|-----|-------------------|
| 1. | JN1BAAV37Z0470004 | 6. | JN1BAAV37Z0470009 |
| 2. | JN1BAAV37Z0470005 | 7. | JN1BAAV37Z0470010 |
| 3. | JN1BAAV37Z0470006 | 8. | JN1BAAV37Z0470011 |
| 4. | JN1BAAV37Z0470007 | 9. | JN1BAAV37Z0470013 |
| 5. | JN1BAAV37Z0470008 | 10. | JN1BAAV37Z0470014 |