

Recall Detail	
<b>Ref No</b>	<b>10000505</b>
<b>Manufacturer</b>	JAC Motors
<b>Vehicle Class</b>	Light Goods Vehicle
<b>Model/Type</b>	LE050
<b>Dealer (phone no)</b>	Sime Darby Motor Services Limited (Tel: 39138800)
<b>Subject</b>	Front axle brake
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	In some countries, JAC Motors received customer feedback that they feel some vibration when applying brake. JAC provided the proactive remedial solution to tackle this symptom.
<b>Remedial Action</b>	Replace with new version brake chamber and bracket
<b>Build Dates</b>	2013-2014
<b>Launch Date</b>	6/1/2015
<b>Tentative Date of Recall Completion</b>	31/12/2015

1	LJ11KEBD0D8010672
2	LJ11KEBD2D8010673
3	LJ11KEBD1E8001139
4	LJ11KEBD6E8001136
5	LJ11KEBD8E8001137
6	LJ11KEBDXE8001138
7	LJ11KEBD8E8001140
8	LJ11KEBD8E8001133
9	LJ11KEBD7E8005048
10	LJ11KEBD1E8005045
11	LJ11KEBD6E8007079
12	LJ11KEBD3E8005046
13	LJ11KEBD7E8005051
14	LJ11KEBD9E8005049
15	LJ11KEBD5E8005047
16	LJ11KEBDXE8005044
17	LJ11KEBD2E8001134
18	LJ11KEBD4E8001135
19	LJ11KEBD5E8005050
20	LJ11KEBD6E8007082

21	LJ11KEBD2E8007080
22	LJ11KEBD4E8007078
23	LJ11KEBD0E8007076
24	LJ11KEBD2E8007077
25	LJ11KEBD9E8007075
26	LJ11KEBD4E8007081
27	LJ11KEBD4E8011843
28	LJ11KEBD6E8011844
29	LJ11KEBD8E8011845
30	LJ11KEBDXE8011846
31	LJ11KEBD1E8011847
32	LJ11KEBD3E8011848
33	LJ11KEBD5E8011849
34	LJ11KEBD1E8011850
35	LJ11KEBD3E8011851
36	LJ11KEBD5E8011852
37	
38	
39	
40	