

Recall Detail

Ref No	10000526
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Alphard
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Inspection of ABS Actuator
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The recall involves Anti-Lock Braking system (ABS), Traction Control System (TRAC), and Vehicle Stability Control System (VSC) which are controlled by the ABS actuator. Due to the improper shape of a component inside the ABS actuator, there is a possibility that a resin component could be damaged during its press fitting assembly, creating minute resin fragment(s) which could become stuck in the actuator. If this occurs, the ABS actuator may cause some issues.
Remedial Action	Inspect and if necessary replace the ABS actuator
Build Dates	January 2015
Launch Date	27 May 2015
Tentative Date of Recall Completion	December 2017

1	JTNGK3DH308000176
2	JTNGK3DH408000199
3	JTNGK3DH608000155
4	JTNGK3DH708000164
5	JTNGK3DH808000156
6	JTNGK3DHX08000174