

Recall Detail

Ref No	10000536
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	SC430
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Replacement of Front Passenger Airbag Inflator
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	This is a supplemental recall campaign related to the recall of replacement of front passenger airbag inflator in 2013. The front passenger air bag inflators could have been assembled with improperly manufactured propellant wafers. It could cause the inflator to rupture and the front passenger air bag to deploy abnormally in a crash, which could result in increase of the risk of injury to the occupant.
Remedial Action	Replace the front passenger air bag inflator
Build Dates	October 2003 ~ June 2007
Launch Date	17 July 2015
Tentative Date of Recall Completion	December 2018

1	JTHFN45Y109011956
2	JTHFN45Y209018480
3	JTHFN45Y709021536
4	JTHFN48Y009000491
5	JTHFN48Y100060316
6	JTHFN48Y200058574
7	JTHFN48Y200062365
8	JTHFN48Y200070031
9	JTHFN48Y209009760
10	JTHFN48Y300047387
11	JTHFN48Y309003675
12	JTHFN48Y309004695
13	JTHFN48Y400062951
14	JTHFN48Y500053868
15	JTHFN48Y500066555
16	JTHFN48Y600062448
17	JTHFN48Y609000267
18	JTHFN48Y609005288
19	JTHFN48Y700059364
20	JTHFN48Y709005252
21	JTHFN48Y800057364

22	JTHFN48Y900051346
23	JTHFN48Y900063982
24	JTHFN48Y900069104
25	JTHFN48YX09000322