

Recall Detail

Ref No	10000539
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Prius V / Auris
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Update of software for both motor/generator control ECU and hybrid control ECU
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The current software settings for the motor/generator control ECU and hybrid control ECU could result in higher thermal stress in certain transistors, potentially causing them to become damaged. If this happens, various warning lights will illuminate and the vehicle can enter a failsafe mode. In rare circumstances, the hybrid system might shut down while the vehicle is being driven, resulting in the loss of power and the vehicle coming to a stop.
Remedial Action	Update of ECU software
Build Dates	Prius V: March 2012 ~ November 2014 Auris: May 2012 ~ September 2012
Launch Date	15 July 2015
Tentative Date of Recall Completion	December 2018

1	JTDZS3EU003032590
2	JTDZS3EU10J001036
3	JTDZS3EU203018142
4	JTDZS3EU203030503
5	JTDZS3EU203065753
6	JTDZS3EU203066403
7	JTDZS3EU303043129
8	JTDZS3EU303063588
9	JTDZS3EU303083971
10	JTDZS3EU603013879
11	JTDZS3EU603045389
12	JTDZS3EU703090986
13	JTDZS3EU903024892
14	JTDZS3EU903060386
15	JTDZS3EU903085577
16	JTDZS3EUX03038896
17	JTDZS3EUX03070618
18	JTDZS3EUX0J000113
19	JTDZS3EUX0J001438
20	SB1KS56E00E071869

21	SB1KS56E10E070715
22	SB1KS56E10E070942
23	SB1KS56E30E066584
24	SB1KS56E30E069601
25	SB1KS56E30E071980
26	SB1KS56E30E072689
27	SB1KS56E40E072782
28	SB1KS56E50E066652
29	SB1KS56E50E070264
30	SB1KS56E80E070646
31	SB1KS56E80E070811
32	SB1KS56EX0E070793