

Recall Detail

Ref No	10000546
Manufacturer	Renault
Vehicle Class	Private Car
Model/Type	CLIO GT
Dealer (phone no)	29273555
Subject	Checking the front flexible brake hose
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Risk of damage to front flexible brake hose by the front wheel arch liner. The warning light for a brake fluid level may come on or reduction in brake system efficiency.
Remedial Action	If necessary, replace the front flexible brake hose and wheel arch
Build Dates	2015
Launch Date	16 September 2015
Tentative Date of Recall Completion	31 March 2016

1	VF15R40SE52806718
2	VF15R40SE52806719