

Recall Detail	
Ref No.	10000552
Manufacturer	Land Rover
Vehicle Class	N1 – Light Goods Vehicle
Model/Type	Defender
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2121 7100 or 2820 5150 / service@landrover.com.hk)
Subject	Front Axle Case Flange Reinforcement Brackets
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The front wheel, hub assembly and suspension might collapsed up into the wheel arch due to oil leaks from end of the front axle case
Remedial Action	Install reinforcement brackets to both ends of the axle assembly
Build Dates	2011-2012
Launch Date	11 Sept 2015
Tentative Date of Recall Completion	31 December 2022

1.	SALLDHMP7CA418039
2.	SALLDHMP7CA418492
3.	SALLDHMP7CA419470
4.	SALLDHMP7CA420155
5.	SALLDHMP7CA421941
6.	SALLDHMP7CA422842
7.	SALLDHMP7CA423534
8.	SALLDHMP7CA424079
9.	SALLDHMP7CA424636
10.	SALLDHMP7CA424776
11.	SALLDHMP7CA426100
12.	SALLDHMP7CA426130
13.	SALLDHMP7CA426315
14.	SALLDHMP7CA426339
15.	SALLDHMP7CA426546
16.	SALLDHMP7CA427208
17.	SALLDHMR7CA413414
18.	SALLDHMR7CA416631
19.	SALLDHMS7BA405691
20.	SALLDHMS7BA406651

21.	SALLDHMS7BA406703
22.	SALLDHMS7BA406890
23.	SALLDHMS7BA409082
24.	SALLDHMS7BA409107
25.	SALLDHMS7BA409141
26.	SALLDHMS7BA409182
27.	SALLDHMS7BA409258
28.	SALLDHMS7BA409318
29.	SALLDHMS7BA410022
30.	SALLDHMS7BA410025
31.	SALLDHMS7BA410085
32.	SALLDHMS7BA822204
33.	SALLDHMS7BA822220
34.	SALLDHMS7BA822232
35.	SALLDHMS7BA822266
36.	SALLDHMS7BA822288
37.	SALLDHMS7BA822294
38.	SALLDHMS7BA822298
39.	SALLDHMS7BA822320
40.	SALLDHMS7BA822326
41.	SALLDHMS7BA822346
42.	SALLDHMS7BA822366
43.	SALLDHMS7BA822384
44.	SALLDHMS7BA822392