

Recall Detail	
Ref No	10000563
Manufacturer	Rolls-Royce
Vehicle Class	Passenger Car
Model/Type	Phantom
Dealer (phone no)	31936999
Subject	Curtain Air Bag Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	An extremely small number of side curtain airbags provided by a sub-supplier may not have been manufactured to specification. As a result it is possible that the airbag might not position perfectly on deployment.
Remedial Action	Check affected vehicles and airbags will be replaced if necessary
Build Dates	15-04-2015 – 14-10-2015
Launch Date	04/12/2015
Tentative Date of Recall Completion	31/05/2016

1	UH28403
2	UH28404
3	UH28407
4	UH28711