

Recall Detail

| | |
|---|---|
| Ref No | 10000570 |
| Manufacturer | Suzuki Motor Corporation |
| Vehicle Class | Motorcycle |
| Model/Type | AN650ZL3-4, SFV650L3, DL650AL2-4, GSX650L2_GSF650L2, GSF1250_GSX1250L2-4 |
| Dealer (phone no) | Cheung Tai Hong Holdings (Motor Vehicle) Ltd. (2523 2537) |
| Subject | Tappet Recall Campaign |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | Contamination between the tappet and cam may cause the hardened surface of the tappet to peel if the surface shape of the tappet is convex. If the hardness of the inner part of the tappet is at the low end of the design specification, both tappet and cam can wear, increasing the tappet clearance, may cause abnormal noise and in the worst case can cause the engine to stall. |
| Remedial Action | Change Related Parts |
| Build Dates | 2012 -2014 |
| Launch Date | January 22, 2016 |
| Tentative Date of Recall Completion | End of 2017 |

| | |
|----|-------------------|
| 1 | JS1BU112100100570 |
| 2 | JS1BU112100101777 |
| 3 | JS1BU112100101827 |
| 4 | JS1BU112100102314 |
| 5 | JS1BU112100102318 |
| 6 | JS1BU112100102409 |
| 7 | JS1BU112100102410 |
| 8 | JS1BU112100103314 |
| 9 | JS1BU112100103325 |
| 10 | JS1BU112100103328 |
| 11 | JS1BU112100103768 |
| 12 | JS1BU112100103769 |
| 13 | JS1BU112100103785 |
| 14 | JS1BU112100103794 |
| 15 | JS1BU112100103798 |
| 16 | JS1BU112100103855 |
| 17 | JS1BU112100103856 |
| 18 | JS1BU112100103857 |

| | |
|----|-------------------|
| 19 | JS1BU112100103859 |
| 20 | JS1BU112100103870 |
| 21 | JS1BU112100103983 |
| 22 | JS1BU112100104020 |
| 23 | JS1BU112100104086 |
| 24 | JS1BU112100104120 |
| 25 | JS1BU112100104135 |
| 26 | JS1BU112100104958 |
| 27 | JS1BU112100104962 |
| 28 | JS1BU112100104987 |
| 29 | JS1BU112100104995 |
| 30 | JS1BU112100105044 |
| 31 | JS1BU112100105047 |
| 32 | JS1BU112100105225 |
| 33 | JS1BU112100105232 |
| 34 | JS1CX111100112062 |
| 35 | JS1CX111100112316 |
| 36 | JS1CX111100112412 |

| | |
|----|-------------------|
| 37 | JS1C7111100109342 |
| 38 | JS1C7111100109572 |
| 39 | JS1C7111100109610 |
| 40 | JS1C7111100109633 |
| 41 | JS1C7111100109643 |
| 42 | JS1C7111100114683 |
| 43 | JS1C7111100114715 |
| 44 | JS1C7111100114716 |
| 45 | JS1CJ135100107181 |
| 46 | JS1CJ135100107213 |
| 47 | JS1CZ123100101749 |
| 48 | JS1CZ123100102003 |
| 49 | JS1CH113100117210 |
| 50 | JS1CH135100108583 |
| 51 | JS1CH135100108587 |
| 52 | |
| 53 | |
| 54 | |
| 55 | |
| 56 | |
| 57 | |
| 58 | |
| 59 | |
| 60 | |
| 61 | |
| 62 | |
| 63 | |
| 64 | |
| 65 | |
| 66 | |
| 67 | |
| 68 | |
| 69 | |
| 70 | |
| 71 | |
| 72 | |
| 73 | |
| 74 | |
| 75 | |
| 76 | |

| | |
|-----|--|
| 77 | |
| 78 | |
| 79 | |
| 80 | |
| 81 | |
| 82 | |
| 83 | |
| 84 | |
| 85 | |
| 86 | |
| 87 | |
| 88 | |
| 89 | |
| 90 | |
| 91 | |
| 92 | |
| 93 | |
| 94 | |
| 95 | |
| 96 | |
| 97 | |
| 98 | |
| 99 | |
| 100 | |
| 101 | |
| 102 | |
| 103 | |
| 104 | |
| 105 | |
| 106 | |
| 107 | |
| 108 | |
| 109 | |
| 110 | |
| 111 | |
| 112 | |
| 113 | |
| 114 | |
| 115 | |
| 116 | |