

Recall Detail	
Ref No	10000580
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	7 series (G11 and G12)
Dealer (phone no)	31936688
Subject	Replace the airbag control unit
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	As part of ongoing quality analysis at BMW, it has been established that, in the case of heavy acceleration or deceleration, this may lead to an internal control unit fault in extremely rare cases. This may lead to a short-term failure of the airbag control unit.
Remedial Action	Replace the airbag control unit
Build Dates	10/2014-12/2015
Launch Date	04/04/2016
Tentative Date of Recall Completion	31/10/2016

1	G522700
2	G522701
3	G522702
4	G522703
5	G522706
6	G522708
7	G522709
8	G522713
9	G522714
10	G522721
11	G522733
12	G522735
13	G522736
14	G522738
15	G522740
16	G522741
17	G522743
18	G522744
19	G522775
20	G522802
21	G522805

22	G522852
23	G522855
24	G522861
25	G522864
26	G522866
27	G522872
28	G522879
29	G522881
30	G522882
31	G522885
32	G522886
33	G522891
34	G522892
35	G522897
36	G522899
37	G522900
38	G522902
39	G522903
40	G522907
41	G522908
42	G522909

43	G522910
44	G522911
45	G522912
46	G522913
47	G522942
48	G522944
49	G522951
50	G522953
51	G522954
52	G522955
53	G522956
54	G522957
55	G522958
56	G522959
57	G522960
58	G522961
59	G522962
60	G522964
61	G522966
62	G522968
63	G522972
64	G522973
65	G522980
66	G523000
67	GD99680
68	GD99687
69	GD99691
70	GD99696
71	GD99697
72	GD99698
73	GD99699
74	GD99700
75	GD99701
76	GD99702
77	GD99760
78	GD99761
79	GD99762
80	GD99768
81	GD99769
82	GD99770

83	GD99771
84	GD99778
85	GD99779
86	GD99780
87	GD99781
88	GD99783
89	GD99784
90	GD99786
91	GD99787
92	GD99789
93	GD99790
94	GD99792
95	GD99793
96	GD99796
97	GD99798
98	GD99799