

Recall Detail	
Ref No	10000592
Manufacturer	SUZUKI MOTOR CORPORATION
Vehicle Class	Private Car
Model/Type	SOLIO (AUK412)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Reprogramming of Airbag Control Module
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Software of the Airbag Control Module should be reprogrammed, to address the airbag warning lamp would be illuminated issue.
Remedial Action	Reprogramming of Airbag Control Module
Build Dates	2016
Launch Date	30/05/2016
Tentative Date of Recall Completion	29/05/2017

1	MA26S100376
2	MA36S103784
3	MA36S110376
4	MA36S110452
5	MA36S110529
6	MA36S110574
7	MA36S110708
8	MA36S110741
9	MA36S110841
10	MA36S110880
11	MA36S110936
12	MA36S111015
13	MA36S111079
14	MA36S111140
15	MA36S111272
16	MA36S111336
17	MA36S111352
18	MA36S111418
19	MA36S111519
20	MA36S111545

21	MA36S111643
22	MA36S111671
23	MA36S111810
24	MA36S111866
25	MA36S112041
26	MA36S112100
27	MA36S112149
28	MA36S112278
29	MA36S112387
30	MA36S112433
31	MA36S112538
32	MA36S112578
33	MA36S112661
34	MA36S112807
35	MA36S112930
36	MA36S112978
37	MA36S113077
38	MA36S113209
39	MA36S113264
40	MA36S113302

41	MA36S113380
42	MA36S113535
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	

81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	