

## Recall Detail

<b>Ref No</b>	<b>10000595</b>
<b>Manufacturer</b>	INFINITI
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Q50 (V37)
<b>Dealer (phone no)</b>	Honest Motors Ltd. (Tel: 221682228)
<b>Subject</b>	Reprogram DAS Control Unit
<b>Progress</b>	Running
<b>Affected Vehicle Identification Number (VIN)</b>	List as below
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	When the engine was started after parking with steering turning, the ECU (Electronic Control Units) of DAS (Direct Adaptive Steering) may miscalculate the steering turning angle incorrectly under the voltage reduction of the battery at cranking and this could cause a difference between the steering wheel angle and the tire turning angle. In some extreme cases, it may not turn as the driver intends.
<b>Remedial Action</b>	Reprogram DAS Control Unit
<b>Build Dates</b>	24 FEB 2014 - 23 NOV 2015
<b>Launch Date</b>	07/07/2016
<b>Tentative Date of Recall Completion</b>	07/07/2019

Q50 (V37)

1.	JN1BAAV37Z0470004	21.	JN1BCAV37Z0480396
2.	JN1BAAV37Z0470005	22.	JN1BCAV37Z0480400
3.	JN1BAAV37Z0470006	23.	JN1BCAV37Z0480403
4.	JN1BAAV37Z0470007	24.	JN1BCAV37Z0480408
5.	JN1BAAV37Z0470008	25.	JN1BCAV37Z0480420
6.	JN1BAAV37Z0470009	26.	JN1BCAV37Z0480423
7.	JN1BAAV37Z0470010	27.	JN1BCAV37Z0480428
8.	JN1BAAV37Z0470011	28.	JN1BCAV37Z0480440
9.	JN1BAAV37Z0470013	29.	JN1BCAV37Z0480443
10.	JN1BAAV37Z0470014	30.	JN1BCAV37Z0480453
11.	JN1BAAV37Z0470071	31.	JN1BCAV37Z0480459
12.	JN1BAAV37Z0470073	32.	JN1BCAV37Z0480494
13.	JN1BAAV37Z0470076	33.	JN1BCAV37Z0480504
14.	JN1BAAV37Z0470080	34.	JN1BCAV37Z0480506
15.	JN1BAAV37Z0470081	35.	JN1BCAV37Z0480517
16.	JN1BAAV37Z0470082	36.	JN1BCAV37Z0480518
17.	JN1BAAV37Z0470084	37.	JN1BCAV37Z0480527
18.	JN1BCAV37Z0480368	38.	JN1BCAV37Z0480529
19.	JN1BCAV37Z0480372	39.	JN1BCAV37Z0480532
20.	JN1BCAV37Z0480389	40.	JN1BCAV37Z0480535