

Recall Detail

Ref No	10000608
Manufacturer	Honda
Vehicle Class	Private Car
Model/Type	3.5RL/ KB1
Dealer (phone no)	22168183
Subject	Driver 's & Passenger's Airbag Inflator Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	During of driver's airbag deployment, the inflator body may be ruptured due to excessive internal pressure.
Remedial Action	Replace Driver 's & Passenger's Airbag Inflator
Build Dates	2007
Launch Date	28 July 2016
Tentative Date of Recall Completion	28 July 2016

JH4KB16307C202587	JH4KB16307C204014
JH4KB16307C202588	JH4KB16307C204015
JH4KB16307C202801	JH4KB16307C204046
JH4KB16307C202802	JH4KB16307C204047
JH4KB16307C202855	JH4KB16307C204182
JH4KB16307C202856	JH4KB16307C204183
JH4KB16307C202857	JH4KB16307C204185
JH4KB16307C203326	JH4KB16307C204188
JH4KB16307C203327	JH4KB16307C204189
JH4KB16307C203328	JH4KB16307C204294
JH4KB16307C203543	JH4KB16307C204852
JH4KB16307C203544	JH4KB16307C204887
JH4KB16307C203603	JH4KB16307C205039
JH4KB16307C203719	JH4KB16307C205040
JH4KB16307C203740	JH4KB16307C205083
JH4KB16307C203741	JH4KB16307C205521
JH4KB16307C203769	JH4KB16307C205523
JH4KB16307C203770	JH4KB16307C205524
JH4KB16307C203990	