

Recall Detail	
Ref No.	10000611
Manufacturer	Jaguar
Vehicle Class	M1 – Private Car
Model/Type	XF, XJ
Dealer (phone no. / e-mail)	British Motors Limited - (Tel: 2821 7100 or 2820 5150 / service@landrover.com.hk)
Subject	Drive Belt Idler Pulley
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	A bolt retaining the accessory drive belt idler pulley may fail leading to a loss of accessory drive due to painted finish on the dust shields.
Remedial Action	Replace modified idler pulley
Build Dates	2013 to 2015
Launch Date	1 Sept 2016
Tentative Date of Recall Completion	31 December 2022

1. SAJAC05M0DPS79651
2. SAJAC05M0DPU04602
3. SAJAC05M2EPU20916
4. SAJAC05M2EPU35478
5. SAJAC05M3DPS69647
6. SAJAC05M3DPS79837
7. SAJAC05M3DPS94712
8. SAJAC05M3FPU41629
9. SAJAC05M3FPU60035
10. SAJAC05M3FPU66899
11. SAJAC05M4DPS77403
12. SAJAC05M4DPS83010
13. SAJAC05M4DPS88496
14. SAJAC05M5DPU01405
15. SAJAC05M6DPS56052
16. SAJAC05M6DPS70856
17. SAJAC05M6DPS72297
18. SAJAC05M6DPS84062
19. SAJAC05M6DPS96566
20. SAJAC05M6DPS99466
21. SAJAC05M6FPU52673

22. SAJAC05M7DPS84054
23. SAJAC05M7DPU06895
24. SAJAC05M7FPU73872
25. SAJAC05M8DPS93393
26. SAJAC05M8DPU07943
27. SAJAC10M2DPV56975
28. SAJAC10MXDPV56979
29. SAJAC20M0DPV49903
30. SAJAC20M0DPV52171
31. SAJAC20M2DPV57775
32. SAJAC20M3DPV49474
33. SAJAC20M4DPV52674
34. SAJAC20M4DPV56403
35. SAJAC20M6DPV54619
36. SAJAC20M7DPV49834
37. SAJAC20M7DPV56055
38. SAJAC20M7EPV71530
39. SAJAC20M8DPV49843
40. SAJAC20M9DPV49477
41. SAJAC20M9EPV61128
42. SAJAC22M2EPV71738

