

Recall Detail

Ref No	10000615
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	RX200t/RX350/RX450h
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Replacement of passenger airbag
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	It is related to the "hybrid" type front passenger air bag inflator with which the burst disk in some inflators may have been improperly welded and/or misassembled. This could result in the partial inflation of the front passenger air bag when the vehicle is parked and unoccupied for a period of time.
Remedial Action	Replace passenger airbag assembly
Build Dates	December 2015 ~ April 2016
Launch Date	14 September 2016
Tentative Date of Recall Completion	December 2017

1	JTJBAMCA002003077
2	JTJBAMCA002003211
3	JTJBAMCA002003273
4	JTJBAMCA202002982
5	JTJBAMCA302002960
6	JTJBAMCA402003194
7	JTJBAMCA502006539
8	JTJBAMCA602003018
9	JTJBAMCA802002517
10	JTJBAMCA802002629
11	JTJBAMCA802003344
12	JTJBAMCAX02002583
13	JTJBAMCAX02003409
14	JTJBGMCAX02003793
15	JTJBZMCA102007437
16	JTJBZMCA702006499
17	JTJBZMCA702006566
18	JTJZAMCA302002164