

Recall Detail	
Ref No	10000616
Manufacturer	Mitsubishi Motors Corporation
Vehicle Class	Light Goods Vehicle
Model/Type	MINICAB-MiEV (U67V)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Horn
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to inappropriate material for the internal electric junction in the horn, improper contact may occur due to oxide coating generated by repetitive water intrusion at the internal electric junction. As a result, the horn may not honk.
Remedial Action	Replacement of horn
Build Dates	2012
Launch Date	5/10/2016
Tentative Date of Recall Completion	4/10/2017

1	U67V-0002912
2	U67V-0002938
3	U67V-0100404
4	U67V-0100405
5	U67V-0100406
6	U67V-0100407
7	U67V-0100408
8	U67V-0100409
9	U67V-0100410
10	U67V-0100411
11	U67V-0100413
12	U67V-0100416
13	U67V-0100418
14	U67V-0100419
15	U67V-0100420
16	U67V-0100421
17	U67V-0100422
18	U67V-0100424
19	
20	

21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	