

## Recall Detail

<b>Ref No</b>	<b>10000619</b>
<b>Manufacturer</b>	Subaru
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	SUBARU Legacy / Outback
<b>Dealer (phone no)</b>	Motor Image Kowloon Limited (23936118)
<b>Subject</b>	Front wiper motor bottom covers
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Affected vehicles have been fitted with faulty front wiper motor bottom covers which may allow foreign objects or obstructions, such as dirt or mud, to enter into the internal parts of the windshield wiper mechanism. This may cause the windshield wiper to “park” at a higher position on the windshield. In that event, the wiper will continuously attempt to return to its original position and the continuous arc-discharge may cause the windshield wiper mechanism to overheat, which may in turn cause the part to melt and potentially pose a fire risk.
<b>Remedial Action</b>	Replace the front wiper motor bottom covers with countermeasure parts
<b>Build Dates</b>	2010-2014
<b>Launch Date</b>	28 October 2016
<b>Tentative Date of Recall Completion</b>	31 December 2018

1	BM9-005690	16	BM9-009396
2	BM9-005691	17	BM9-009786
3	BM9-005694	18	BM9-009789
4	BM9-006348	19	BM9-009809
5	BM9-006358	20	BM9-009841
6	BM9-008156	21	BM9-009848
7	BM9-008233	22	BM9-009871
8	BM9-008240	23	BM9-009899
9	BM9-008271	24	BM9-009906
10	BM9-008275	25	BM9-009942
11	BM9-008292	26	BM9-009964
12	BM9-008293	27	BM9-009982
13	BM9-009295	28	BM9-010496
14	BM9-009323	29	BM9-010521
15	BM9-009360	30	BM9-010529

31	BM9-010544
32	BM9-010557
33	BM9-010597
34	BM9-017006
35	BM9-017061
36	BM9-017228
37	BM9-017245
38	BR9-010903
39	BR9-011138
40	BR9-011173
41	BR9-013264
42	BR9-013277
43	BR9-013287
44	BR9-017083
45	BR9-017202
46	BR9-017407
47	BR9-017431
48	BR9-017488
49	BR9-017496
50	BR9-017626
51	BR9-019072
52	BR9-019077
53	BR9-019097
54	BR9-019110
55	BR9-019988
56	BR9-020047
57	BR9-020119
58	BR9-020122
59	BR9-020128
60	BR9-020196
61	BR9-021876
62	BR9-021907
63	BR9-022025
64	BR9-024031
65	BR9-024126
66	BR9-024201
67	BR9-024265
68	JF1BR5KC2CG033439
69	JF1BR9K95AG003770
70	JF1BR9K95AG004287

71	JF1BR9K95AG004321
72	JF1BR9K95AG005464
73	JF1BR9K95AG007402
74	JF1BR9K95AG007593
75	JF1BR9K95AG007628
76	JF1BR9K95AG007738
77	JF1BR9K95AG007743
78	JF1BR9K95AG007763
79	JF1BR9K95AG007796
80	JF1BR9K95AG007828
81	JF1BR9K95AG007889
82	JF1BR9K95AG008267
83	JF1BR9K95AG008610
84	JF1BR9K95AG008627
85	JF1BR9K95AG008700
86	JF1BR9K95AG008809
87	JF1BR9K95AG008814
88	JF1BR9K95AG008858
89	JF1BR9K95AG008972
90	JF1BR9K95AG009243
91	JF1BR9K95AG009469
92	JF1BR9K95AG009572
93	JF1BR9K95AG009638
94	JF1BR9K95AG011111
95	JF1BR9K95AG011179
96	JF1BR9K95AG011697
97	JF1BR9K95AG011772
98	JF1BR9K95AG012115
99	JF1BR9K95AG012184
100	JF1BR9K95AG012313
101	JF1BR9K95AG012405
102	JF1BR9K95AG012573
103	JF1BR9K95AG012721
104	JF1BR9K95AG012883
105	JF1BR9K95AG013124
106	JF1BR9K95AG013140
107	JF1BR9K95AG013642
108	JF1BR9K95AG014038
109	JF1BR9K95BG024465
110	JF1BR9K95BG024661

111	JF1BR9K95BG025183
112	JF1BR9K95BG027441
113	JF1BR9K95BG027482
114	JF1BR9K95BG028219
115	JF1BR9K95CG033480
116	JF1BR9K95CG034061
117	JF1BR9K95CG034105
118	JF1BR9K95CG034113
119	JF1BR9K95CG034126
120	JF1BR9K95CG034229
121	JF1BR9K95CG034238
122	JF1BR9K95CG034240
123	JF1BR9K95CG034523
124	JF1BR9K95CG034581
125	JF1BR9K95CG035014
126	JF1BR9K95CG035016
127	JF1BR9K95CG035029
128	JF1BR9K95CG036159
129	JF1BR9K95CG036160
130	JF1BR9K95CG036170
131	JF1BRMKC5DG044046
132	JF1BRMKC5DG044073
133	JF1BRMKC5DG044132