

Recall Detail

Ref No	10000629
Manufacturer	Bentley
Vehicle Class	Private car
Model/Type	Bentayga
Dealer (phone no)	Ap Lei Chau Service Center Tel: 25537713 Kowloon Bay Service Center Tel: 22621288 Tsuen Wan Service Center Tel: 21119679
Subject	Bentley Bentayga bolted joint over check
Progress	In process
Affected Vehicle Identification Number (VIN)	If vehicle bought from Hong Kong Authorized Dealers, please see the list as below; If your vehicle bought from Parallel Importer, and the vehicle Build Dates is within this period, please contact our Dealers or Bentley Motors China - Hong Kong regional office (Tel : 36989726).
Description of Defect, how it came to light, and possible consequences if ignored.	The specific bolted joints tightened during the assembly of the vehicle may not have been correctly tightened. As a precaution Bentley are undertaking a check of a small number of specific vehicles.
Remedial Action	Over check the tightening torque of affected vehicles
Build Dates	Manufactured from 5th February 2016 to 5th October 2016
Launch Date	5th December 2016
Tentative Date of Recall Completion	31st March 2017

1	SJAAB14VXHCO11805
2	SJAAB14V6HCO13440
3	SJAAB14VOHCO14499
4	SJAAB14V5HCO15518
5	SJAAB14V8HCO15612
6	SJAAB14V4HCO11394
7	SJAAB14V4HCO12903
8	SJAAB14V2HCO15041