

Recall Detail	
Ref No	10000631
Manufacturer	Rolls-Royce
Vehicle Class	Passenger Car
Model/Type	Ghost
Dealer (phone no)	31936999
Subject	Airbag central sensor replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	The central sensor for the airbag system has been programmed with faulty software. In case the vehicle is involved in either a front or rear accident, the passive restraint systems (front airbags and belt tensioner) will not be activated, leading to an increased risk of injury.
Remedial Action	Replace central airbag sensor
Build Dates	11/2011 – 06/2012
Launch Date	16/11/2016
Tentative Date of Recall Completion	31/05/2017

1	UH16635
2	UH16644
3	UH16648
4	UH16666
5	UH16674
6	UH16676
7	UH16691
8	UH16693
9	UH16696
10	UH16710
11	UH16711
12	UH16730
13	UH16743
14	UH16746
15	UH16748
16	UH16752
17	UH16770
18	UH16787
19	UH22572
20	UH22578
21	UH22583

22	UH22584
23	UH22589
24	UH22590
25	UH22591
26	UH22592
27	UH22606
28	UH22607
29	UH22611
30	UH22615
31	UH22616
32	UH22632
33	UH22633
34	UH22637
35	UH22640
36	UH22645
37	UX66944