

Recall Detail	
Ref No	10000633
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	5 series and 7 series (F07 and F02)
Dealer (phone no)	31936688
Subject	Replace airbag central sensor
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	The airbag central sensor, which measures longitudinal and lateral acceleration, is programmed with faulty software. It is possible that a front-end or rear-end collision will be evaluated incorrectly and the passive restraint systems (front airbags and seat belt tensioners) will not be activated. This kind of situation, requiring restraint system activation, can lead to an increased risk of injury for vehicle occupants.
Remedial Action	Replace airbag central sensor
Build Dates	02.12.2011 - 05.09.2012
Launch Date	23/11/2016
Tentative Date of Recall Completion	31/05/2017

1	B998227
2	C194641
3	C194648
4	C194657
5	C194661
6	C194663
7	C194665
8	C194666
9	C194668
10	C194671
11	C194672
12	C194682
13	C194683
14	C194684
15	C194694
16	C194695
17	C194697
18	C194700
19	C194701

20	C194704
21	C194726
22	C194732
23	C194737
24	C216273
25	C951662
26	C951663
27	C951664
28	CY56243
29	CY56244
30	CY56251
31	CY56254
32	CY84095
33	CY84097
34	CY84098
35	CY84099
36	CY84100
37	CY84103
38	CY84108

39	CY84109
40	CY84112
41	CY84113
42	CY84115
43	CY84117
44	CY84119
45	CY84122
46	CY84127
47	CY84129
48	CY84130
49	CY84131
50	CY84132
51	CY84133
52	CY84134
53	CY84135
54	CY84136
55	CY84137
56	CY84138
57	CY84139
58	CY84140
59	CY84141
60	CY84142
61	CY84143
62	CY84144
63	CY84145
64	CY84146
65	CY84150
66	CY84152
67	CY84155
68	CY84156
69	CY84157
70	CY84158
71	CY84159
72	CY84160
73	CY84161
74	CY84162
75	CY84165
76	CY84166
77	CY84168
78	CY84169

79	CY84172
80	CY84173
81	CY84175
82	CY84176
83	CY84180
84	CY84181
85	CY84182