

## Recall Detail

<b>Ref No</b>	<b>10000640</b>
<b>Manufacturer</b>	Honda
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	FREED GB3
<b>Dealer (phone no)</b>	22168183
<b>Subject</b>	Passenger 's Airbag Inflator Replacement
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	During of passenger's airbag deployment, the inflator body may be ruptured due to excessive internal pressure.
<b>Remedial Action</b>	Replace Passenger 's Airbag Inflator
<b>Build Dates</b>	2012
<b>Launch Date</b>	27 JAN 2017
<b>Tentative Date of Recall Completion</b>	27 JAN 2022

JHMGB3850CC200002	JHMGB3850CC200023
JHMGB3850CC200003	JHMGB3850CC200024
JHMGB3850CC200004	JHMGB3850CC200025
JHMGB3850CC200005	JHMGB3850CC200026
JHMGB3850CC200006	JHMGB3850CC200027
JHMGB3850CC200007	JHMGB3850CC200028
JHMGB3850CC200008	JHMGB3850CC200029
JHMGB3850CC200009	JHMGB3850CC200030
JHMGB3850CC200010	JHMGB3850CC200031
JHMGB3850CC200011	JHMGB3850CC200032
JHMGB3850CC200012	JHMGB3850CC200033
JHMGB3850CC200013	JHMGB3850CC200035
JHMGB3850CC200014	JHMGB3850CC200037
JHMGB3850CC200015	JHMGB3850CC200038
JHMGB3850CC200016	JHMGB3850CC200039
JHMGB3850CC200017	JHMGB3850CC200040
JHMGB3850CC200018	JHMGB3850CC200041
JHMGB3850CC200019	JHMGB3850CC200042
JHMGB3850CC200020	JHMGB3850CC200043
JHMGB3850CC200021	JHMGB3850CC200045
JHMGB3850CC200022	JHMGB3850CC200047

JHMGB3850CC200048  
JHMGB3850CC200050  
JHMGB3850CC200053  
JHMGB3850CC200054  
JHMGB3850CC200055  
JHMGB3850CC200056  
JHMGB3850CC200057  
JHMGB3850CC200058  
JHMGB3850CC200059  
JHMGB3850CC200060  
JHMGB3850CC200061  
JHMGB3850CC200062  
JHMGB3850CC200063  
JHMGB3850CC200064  
JHMGB3850CC200065  
JHMGB3850CC200067  
JHMGB3850CC200068  
JHMGB3850CC200069  
JHMGB3850CC200070  
JHMGB3850CC200071  
JHMGB3850CC200072  
JHMGB3850CC200073  
JHMGB3850CC200074  
JHMGB3850CC200075  
JHMGB3850CC200078  
JHMGB3850CC200079  
JHMGB3850CC200080  
JHMGB3850CC200081  
JHMGB3850CC200082  
JHMGB3850CC200083  
JHMGB3850CC200084  
JHMGB3850CC200085  
JHMGB3850CC200086  
JHMGB3850CC200087  
JHMGB3850CC200088  
JHMGB3850CC200089  
JHMGB3850CC200090  
JHMGB3850CC200091  
JHMGB3850CC200094

JHMGB3850CC200096  
JHMGB3850CC200097  
JHMGB3850CC200098  
JHMGB3850CC200099  
JHMGB3850CC200100  
JHMGB3850CC200101  
JHMGB3850CC200102  
JHMGB3850CC200103  
JHMGB3850CC200104  
JHMGB3850CC200105  
JHMGB3850CC200106  
JHMGB3850CC200107  
JHMGB3850CC200108  
JHMGB3850CC200109  
JHMGB3850CC200110  
JHMGB3850CC200111  
JHMGB3850CC200112  
JHMGB3850CC200113  
JHMGB3850CC200114  
JHMGB3850CC200115  
JHMGB3850CC200116  
JHMGB3850CC200117  
JHMGB3850CC200118  
JHMGB3850CC200119  
JHMGB3850CC200120  
JHMGB3850CC200121  
JHMGB3850CC200122  
JHMGB3850CC200123  
JHMGB3850CC200124  
JHMGB3850CC200125  
JHMGB3850CC200126  
JHMGB3850CC200127  
JHMGB3850CC200128  
JHMGB3850CC200129  
JHMGB3850CC200130  
JHMGB3850CC200131  
JHMGB3850CC200132  
JHMGB3850CC200133  
JHMGB3850CC200134

JHMGB3850CC200142  
JHMGB3850CC200143  
JHMGB3850CC200144  
JHMGB3850CC200145  
JHMGB3850CC200146  
JHMGB3850CC200147  
JHMGB3850CC200148  
JHMGB3850CC200149  
JHMGB3850CC200150  
JHMGB3850CC200151  
JHMGB3850CC200152  
JHMGB3850CC200153  
JHMGB3850CC200154  
JHMGB3850CC200155  
JHMGB3850CC200156  
JHMGB3850CC200157  
JHMGB3850CC200158  
JHMGB3850CC200159  
JHMGB3850CC200160  
JHMGB3850CC200161  
JHMGB3850CC200162  
JHMGB3850CC200163  
JHMGB3850CC200164  
JHMGB3850CC200165  
JHMGB3850CC200166  
JHMGB3850CC200167  
JHMGB3850CC200170  
JHMGB3850CC200171  
JHMGB3850CC200172  
JHMGB3850CC200173  
JHMGB3850CC200174  
JHMGB3850CC200185  
JHMGB3850CC200186  
JHMGB3850CC200187  
JHMGB3850CC200188  
JHMGB3850CC200189  
JHMGB3850CC200190  
JHMGB3850CC200191  
JHMGB3850CC200192

JHMGB3850CC200193  
JHMGB3850CC200194  
JHMGB3850CC200195  
JHMGB3850CC200196  
JHMGB3850CC200197  
JHMGB3850CC200198  
JHMGB3850CC200199  
JHMGB3850CC200200  
JHMGB3850CC200201  
JHMGB3850CC200202  
JHMGB3850CC200204  
JHMGB3850CC200205  
JHMGB3850CC200206  
JHMGB3850CC200207  
JHMGB3850CC200208  
JHMGB3850CC200209  
JHMGB3850CC200211  
JHMGB3850CC200212  
JHMGB3850CC200213  
JHMGB3850CC200214  
JHMGB3850CC200215  
JHMGB3850CC200216  
JHMGB3850CC200218  
JHMGB3850CC200219  
JHMGB3850CC200220  
JHMGB3850CC200223  
JHMGB3850CC200233  
JHMGB3850CC200234  
JHMGB3850CC200235  
JHMGB3850CC200236  
JHMGB3850CC200237  
JHMGB3850CC200238  
JHMGB3850CC200239  
JHMGB3850CC200240  
JHMGB3850CC200242  
JHMGB3850CC200243  
JHMGB3850CC200246  
JHMGB3850CC200247  
JHMGB3850CC200248

JHMGB3850CC200249  
JHMGB3850CC200250  
JHMGB3850CC200255  
JHMGB3850CC200256  
JHMGB3850CC200262  
JHMGB3850CC200263  
JHMGB3850CC200272  
JHMGB3850CC200273  
JHMGB3850CC200274  
JHMGB3850CC200275  
JHMGB3850CC200276  
JHMGB3850CC200277  
JHMGB3850CC200278  
JHMGB3850CC200279  
JHMGB3850CC200280  
JHMGB3850CC200281  
JHMGB3850CC200282  
JHMGB3850CC200283  
JHMGB3850CC200284  
JHMGB3850CC200285  
JHMGB3850CC200286  
JHMGB3850CC200287  
JHMGB3850CC200288  
JHMGB3850CC200289  
JHMGB3850CC200290  
JHMGB3850CC200291  
JHMGB3850CC200302  
JHMGB3850CC200313  
JHMGB3850CC200314  
JHMGB3850CC200315  
JHMGB3850CC200316  
JHMGB3850CC200317  
JHMGB3850CC200318  
JHMGB3850CC200319  
JHMGB3850CC200320  
JHMGB3850CC200321  
JHMGB3850CC200322  
JHMGB3850CC200323  
JHMGB3850CC200329

JHMGB3850CC200330  
JHMGB3850CC200331  
JHMGB3850CC200332  
JHMGB3850CC200333  
JHMGB3850CC200334  
JHMGB3850CC200335  
JHMGB3850CC200341  
JHMGB3850CC200342  
JHMGB3850CC200343  
JHMGB3850CC200344  
JHMGB3850CC200345  
JHMGB3850CC200346  
JHMGB3850CC200347  
JHMGB3850CC200348  
JHMGB3850CC200349  
JHMGB3850CC200358  
JHMGB3850CC200362  
JHMGB3850CC200363  
JHMGB3850CC200364  
JHMGB3850CC200365  
JHMGB3850CC200366  
JHMGB3850CC200367  
JHMGB3850CC200368  
JHMGB3850CC200369  
JHMGB3850CC200373  
JHMGB3850CC200374  
JHMGB3850CC200375  
JHMGB3850CC200376  
JHMGB3850CC200377  
JHMGB3850CC200378  
JHMGB3850CC200379  
JHMGB3850CC200380  
JHMGB3850CC200397  
JHMGB3850CC200398  
JHMGB3850CC200400  
JHMGB3850CC200401  
JHMGB3850CC200402  
JHMGB3850CC200403  
JHMGB3850CC200404

JHMGB3850CC200405  
JHMGB3850CC200406  
JHMGB3850CC200407  
JHMGB3850CC200408  
JHMGB3850CC200409  
JHMGB3850CC200410  
JHMGB3850CC200411  
JHMGB3850CC200415  
JHMGB3850CC200416  
JHMGB3850CC200421  
JHMGB3850CC200422  
JHMGB3850CC200423  
JHMGB3850CC200424  
JHMGB3850CC200425  
JHMGB3850CC200426  
JHMGB3850CC200427  
JHMGB3850CC200428  
JHMGB3850CC200429  
JHMGB3850CC200430  
JHMGB3850CC200431  
JHMGB3850CC200432  
JHMGB3850CC200433  
JHMGB3850CC200434  
JHMGB3850CC200435  
JHMGB3850CC200436  
JHMGB3850CC200437  
JHMGB3850CC200450  
JHMGB3850CC200451  
JHMGB3850CC200452  
JHMGB3850CC200458  
JHMGB3850CC200459  
JHMGB3850CC200460  
JHMGB3850CC200464  
JHMGB3850CC200465  
JHMGB3850CC200466  
JHMGB3850CC200467  
JHMGB3850CC200468  
JHMGB3850CC200469  
JHMGB3850CC200470

JHMGB3850CC200475  
JHMGB3850CC200476  
JHMGB3850CC200477  
JHMGB3850CC200491  
JHMGB3850CC200492  
JHMGB3850CC200493  
JHMGB3850CC200494  
JHMGB3850CC200495  
JHMGB3850CC200496  
JHMGB3850CC200497  
JHMGB3850CC200498  
JHMGB3850CC200499  
JHMGB3850CC200500  
JHMGB3850CC200505  
JHMGB3850CC200506  
JHMGB3850CC200507  
JHMGB3850CC200508  
JHMGB3850CC200509  
JHMGB3850CC200510  
JHMGB3850CC200511  
JHMGB3850CC200512  
JHMGB3850CC200513  
JHMGB3850CC200514  
JHMGB3850CC200515  
JHMGB3850CC200516  
JHMGB3850CC200528  
JHMGB3850CC200529  
JHMGB3850CC200530  
JHMGB3850CC200531  
JHMGB3850CC200532  
JHMGB3850CC200533  
JHMGB3850CC200534  
JHMGB3850CC200535  
JHMGB3850CC200536  
JHMGB3850CC200537  
JHMGB3850CC200540  
JHMGB3850CC200541  
JHMGB3850CC200547  
JHMGB3850CC200548

JHMGB3850CC200549  
JHMGB3850CC200550  
JHMGB3850CC200551  
JHMGB3850CC200552  
JHMGB3850CC200553  
JHMGB3850CC200554  
JHMGB3850CC200555  
JHMGB3850CC200556  
JHMGB3850CC200575  
JHMGB3850CC200576  
JHMGB3850CC200577  
JHMGB3850CC200578  
JHMGB3850CC200579  
JHMGB3850CC200583  
JHMGB3850CC200584  
JHMGB3850CC200585  
JHMGB3850CC200596  
JHMGB3850CC200597  
JHMGB3850CC200598  
JHMGB3850CC200599  
JHMGB3850CC200600  
JHMGB3850CC200601  
JHMGB3850CC200602  
JHMGB3850CC200610  
JHMGB3850CC200622  
JHMGB3850CC200623  
JHMGB3850CC200624  
JHMGB3850CC200625  
JHMGB3850CC200628  
JHMGB3850CC200629  
JHMGB3850CC200630  
JHMGB3850CC200631  
JHMGB3850CC200632  
JHMGB3850CC200633  
JHMGB3850CC200634  
JHMGB3850CC200635  
JHMGB3850CC200636  
JHMGB3850CC200637  
JHMGB3850CC200638

JHMGB3850CC200639  
JHMGB3850CC200642  
JHMGB3850CC200643  
JHMGB3850CC200646  
JHMGB3850CC200647  
JHMGB3850CC200648  
JHMGB3850CC200649  
JHMGB3850CC200650  
JHMGB3850CC200651  
JHMGB3850CC200652  
JHMGB3850CC200653  
JHMGB3850CC200654  
JHMGB3850CC200655  
JHMGB3850CC200656  
JHMGB3850CC200657  
JHMGB3850CC200665  
JHMGB3850CC200668  
JHMGB3850CC200671  
JHMGB3850CC200672  
JHMGB3850CC200673  
JHMGB3850CC200674  
JHMGB3850CC200675  
JHMGB3850CC200676  
JHMGB3850CC200678  
JHMGB3850CC200679  
JHMGB3850CC200680  
JHMGB3850CC200681  
JHMGB3850CC200682  
JHMGB3850CC200683  
JHMGB3850CC200687  
JHMGB3850CC200688  
JHMGB3850CC200690  
JHMGB3850CC200691  
JHMGB3850CC200692  
JHMGB3850CC200693  
JHMGB3850CC200694  
JHMGB3850CC200695  
JHMGB3850CC200696  
JHMGB3850CC200697

JHMGB3850CC200698  
JHMGB3850CC200699  
JHMGB3850CC200700  
JHMGB3850CC200701  
JHMGB3850CC200702  
JHMGB3850CC200703  
JHMGB3850CC200704  
JHMGB3850CC200706  
JHMGB3850CC200707  
JHMGB3850CC200713  
JHMGB3850CC200736  
JHMGB3850CC200741  
JHMGB3850CC200742  
JHMGB3850CC200743  
JHMGB3850CC200744  
JHMGB3850CC200745  
JHMGB3850CC200746  
JHMGB3850CC200747  
JHMGB3850CC200753  
JHMGB3850CC200757  
JHMGB3850CC200758  
JHMGB3850CC200764  
JHMGB3850CC200765  
JHMGB3850CC200766  
JHMGB3850CC200767  
JHMGB3850CC200768  
JHMGB3850CC200769  
JHMGB3850CC200770  
JHMGB3850CC200771  
JHMGB3850CC200777  
JHMGB3850CC200778  
JHMGB3850CC200779  
JHMGB3850CC200780  
JHMGB3850CC200781  
JHMGB3850CC200782  
JHMGB3830CC200001