

## Recall Detail

<b>Ref No</b>	<b>10000643</b>
<b>Manufacturer</b>	Honda
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	ACCORD CP2
<b>Dealer (phone no)</b>	22168183
<b>Subject</b>	Passenger 's Airbag Inflator Replacement
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	During of passenger's airbag deployment, the inflator body may be ruptured due to excessive internal pressure.
<b>Remedial Action</b>	Replace Passenger 's Airbag Inflator
<b>Build Dates</b>	2012
<b>Launch Date</b>	27 JAN 2017
<b>Tentative Date of Recall Completion</b>	27 JAN 2022

JHMCP2670CC200022

JHMCP2670CC201619

JHMCP2670CC201620

JHMCP2670CC201621

JHMCP2670CC201730

JHMCP2670CC201731

JHMCP2670CC201732

JHMCP2670CC201733

JHMCP2630CC200021

JHMCP2630CC200905

JHMCP2630CC201637