

Recall Detail	
Ref No	10000647
Manufacturer	Mitsubishi Motors Corporation
Vehicle Class	Private Car
Model/Type	LANCER (CY3A) / ASX (GA3W)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Reprogram engine ECU
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to inappropriate programming of engine ECU, engine idling speed may become unstable and the engine may be stalled in the worst case scenario.
Remedial Action	Reprogram engine ECU
Build Dates	2011 – 6/2012
Launch Date	28/02/2017
Tentative Date of Recall Completion	27/02/2018

1	JMYSTCY3ABU000201
2	JMYSTCY3ABU000204
3	JMYSTCY3ABU000205
4	JMYSTCY3ABU000206
5	JMYSTCY3ABU000207
6	JMYSTCY3ABU000209
7	JMYSTCY3ABU000226
8	JMYSTCY3ABU000228
9	JMYXTGA3WBZ000102
10	JMYXTGA3WBZ000103
11	JMYXTGA3WBZ000104
12	JMYXTGA3WBZ000105
13	JMYXTGA3WBZ000106
14	JMYXTGA3WBZ000109
15	JMYXTGA3WBZ000110
16	JMYXTGA3WBZ000111
17	JMYXTGA3WBZ000115
18	JMYXTGA3WBZ000116
19	JMYXTGA3WBZ000117
20	JMYXTGA3WBZ000118

21	JMYXTGA3WBZ000119
22	JMYXTGA3WBZ000120
23	JMYXTGA3WBZ000121
24	JMYXTGA3WBZ000122
25	JMYXTGA3WBZ000123
26	JMYXTGA3WBZ000124
27	JMYXTGA3WBZ000125
28	JMYXTGA3WBZ000127
29	JMYXTGA3WBZ000130
30	JMYXTGA3WBZ000132
31	JMYXTGA3WBZ000134
32	JMYXTGA3WBZ000135
33	JMYXTGA3WBZ000139
34	JMYXTGA3WCZ000111
35	JMYXTGA3WCZ000112
36	JMYXTGA3WCZ000113
37	
38	
39	
40	