

## Recall Detail

<b>Ref No</b>	<b>10000665</b>
<b>Manufacturer</b>	Honda
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	FREED GB5
<b>Dealer (phone no)</b>	22168183
<b>Subject</b>	Front Seatbelt Pretensioner Replacement
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Inappropriate material mixture ratio setting in terms of the ignition agent inside of the initiator to activate the pretensioner, This may prevent the pretensioner from working upon collision.
<b>Remedial Action</b>	Replace Front Seatbelt Pretensioner
<b>Build Dates</b>	2017
<b>Launch Date</b>	22 MAR 2017
<b>Tentative Date of Recall Completion</b>	22 MAR 2022

JHMGB5840HC200012  
 JHMGB5840HC200013  
 JHMGB5840HC200014  
 JHMGB5840HC200015  
 JHMGB5840HC200017  
 JHMGB5840HC200018  
 JHMGB5840HC200020  
 JHMGB5840HC200021  
 JHMGB5840HC200022  
 JHMGB5840HC200023  
 JHMGB5840HC200024  
 JHMGB5840HC200025  
 JHMGB5840HC200026  
 JHMGB5840HC200027  
 JHMGB5840HC200028  
 JHMGB5840HC200029  
 JHMGB5840HC200030  
 JHMGB5840HC200031  
 JHMGB5840HC200032  
 JHMGB5840HC200034  
 JHMGB5840HC200035

JHMGB5840HC200036  
 JHMGB5840HC200037  
 JHMGB5840HC200038  
 JHMGB5840HC200039  
 JHMGB5840HC200041  
 JHMGB5840HC200042  
 JHMGB5840HC200043  
 JHMGB5840HC200045  
 JHMGB5840HC200046  
 JHMGB5840HC200047  
 JHMGB5840HC200048  
 JHMGB5840HC200049  
 JHMGB5840HC200050  
 JHMGB5840HC200051  
 JHMGB5840HC200052  
 JHMGB5840HC200053  
 JHMGB5840HC200054  
 JHMGB5840HC200055