Recall Detail		
Ref No	10000669	
Manufacturer	Lexus	
Vehicle Class	Private Car	
Model/Type	LFA/IS250/IS250C	
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)	
Subject	Replacement of Front Passenger Airbag / Inflator	
Progress	Running	
Affected Vehicle Identification Number (VIN)	List as below:	
Description of Defect, how it came to light, and possible consequences if ignored.	According to a Defect Information Report submitted by Takata Corporation, defect in front passenger air bag inflators may arise due to propellant degradation occurring after prolonged exposure to high absolute humidity, high temperatures and high temperature cycling. This could cause the inflator to rupture and the front passenger air bag to deploy abnormally in a crash, which could result in increase of the risk of injury to the occupant.	
Remedial Action	Replace the front passenger air bag / inflator	
<b>Build Dates</b>	LFA: January 2011 ~ June 2012 IS250/IS250C: March 2012 ~ August 2012	
Launch Date	11 January 2017	
Tentative Date of Recall Completion	December 2018	

1	JTHHX8BH301000227
2	JTHHX8BH501000018
3	JTHHX8BH601000366
4	JTHBK262005174661
5	JTHBK262205169431
6	JTHBK262205170031
7	JTHBK262205174645
8	JTHBK262205174693
9	JTHBK262205179019
10	JTHBK262305169499
11	JTHBK262305183063
12	JTHBK262305185296
13	JTHBK262405169818
14	JTHBK262505169682
15	JTHBK262505176826
16	JTHBK262605179038
17	JTHBK262705169621
18	JTHBK262705181199
19	JTHBK262805167358
20	JTHBK262905167465

21	JTHBK262905171662
22	JTHBK262905185268
23	JTHBK262X05185246
24	JTHFK252002525962
25	JTHFK252002526674
26	JTHFK252302524644