

Recall Detail

Ref No	10000676
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	A-Class, C-Class, E-Class & GLC-Class / 117, 204, 205, 212, 213 & 253
Dealer (phone no)	Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Kwai Chung Service Centre: 2427 3355 Zung Fu Yuen Long Service Centre: 2473 3171
Subject	Perform SCN coding in various control units (5498949)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>One or several control units may have been coded incorrectly on the affected vehicles.</p> <p>Faulty coding may trigger various malfunctions in affected vehicles. Therefore, it cannot be ruled out that, depending on the control unit, there will be an effect on the safety and/or the emissions of the vehicle. For example, an incorrect airbag may be triggered in certain vehicles in case of an accident in isolated cases, the airbag control unit may not recognize the status of the seat belt buckles, the engine control unit may be coded with the wrong maximum speed or various support systems may not work. This may pose an increased risk of injury for the vehicle occupants.</p>
Remedial Action	Recode the affected control units on affected vehicle as a precautionary measure.
Build Dates	20/09/2013 - 22/10/2016
Launch Date	06/04/2017

1	WDC2533462F164961
2	WDC2533462F178212
3	WDC2533462F179100
4	WDC2533462F181146
5	WDC2533462F183431
6	WDC2539462F162453
7	WDC2539462F177157
8	WDC2539462F177279
9	WDC2539462F177552
10	WDC2539462F178170
11	WDC2539462F178738
12	WDC2539462F179286
13	WDC2539462F182996
14	WDD1173432N374847
15	WDD2040482A952505
16	WDD2050862F214438
17	WDD2053422F438820
18	WDD2053452F450391
19	WDD2054422F465066
20	WDD2120342A902764
21	WDD2130422A139797
22	WDD2130422A141834
23	WDD2130422A142777
24	WDD2130422A145261
25	WDD2130422A147804
26	WDD2130482A145280