

Recall Detail	
Ref No	<b>10000695</b>
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	X1 and 4 series (F48 and F33)
Dealer (phone no)	31936688
Subject	Replacing the airbag
Progress	<b>Running</b>
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	The ignition squibs for various airbag modules may not have been manufactured according to specifications. If an ignition squib is faulty, the airbag does not trip when needed.
Remedial Action	Replace the affected airbag modules
Build Dates	16.09.2016 - 27.01.2017
Launch Date	27/02/2017
Tentative Date of Recall Completion	31/08/2017

1	<b>5C21002</b>
2	<b>5C21003</b>
3	<b>5C21008</b>
4	<b>5C21009</b>
5	<b>5C21010</b>
6	<b>5C21019</b>
7	<b>5C21032</b>
8	<b>5C21041</b>
9	<b>5C21043</b>
10	<b>5C21044</b>
11	<b>5C21054</b>
12	<b>5C21055</b>
13	<b>5C21056</b>
14	<b>5C21057</b>
15	<b>5C21058</b>
16	<b>5C21059</b>
17	<b>5F44088</b>
18	<b>5F44090</b>
19	<b>5F44108</b>
20	<b>5F44131</b>
21	<b>5F44132</b>