

Recall Detail

Ref No	10000699
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	G-Class / 463
Dealer (phone no)	Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Kwai Chung Service Centre: 2427 3355 Zung Fu Yuen Long Service Centre: 2473 3171
Subject	Replace steering shaft universal joint on steering gear (4692142)
Progress	Running
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.
Description of Defect, how it came to light, and possible consequences if ignored.	The steering coupling on affected vehicles may have been tightened with an insufficient torque. In this case, the universal joint gearing may wear in the event of an increased application of force. As a result, the steering wheel would no longer be connected to the steering gear, and the vehicle would no longer be steerable. This would increase the risk of an accident.
Remedial Action	Replace the steering shaft universal joint on affected vehicles as a precautionary measure.
Build Dates	15/01/2013 - 14/03/2016
Launch Date	12/06/2017
Tentative Date of Recall Completion	31/12/2017

1 WDB4632361X214335

2 WDB4632361X226136

3 WDB4632362X207139

4 WDB4632362X219979

5	WDB4632362X222468
6	WDB4632362X222481
7	WDB4632362X225236
8	WDB4632362X225305
9	WDB4632362X226380
10	WDB4632362X227783
11	WDB4632362X233699
12	WDB4632362X236107
13	WDB4632362X241459
14	WDB4632721X224464
15	WDB4632721X233556
16	WDB4632722X206196
17	WDB4632722X206258
18	WDB4632722X206556
19	WDB4632722X206881
20	WDB4632722X206961
21	WDB4632722X207412
22	WDB4632722X208848
23	WDB4632722X210054
24	WDB4632722X210567
25	WDB4632722X214358
26	WDB4632722X214362
27	WDB4632722X214455
28	WDB4632722X218787
29	WDB4632722X219414
30	WDB4632722X220415
31	WDB4632722X220779
32	WDB4632722X220995
33	WDB4632722X221144
34	WDB4632722X221238
35	WDB4632722X221331
36	WDB4632722X222397
37	WDB4632722X222460
38	WDB4632722X223912
39	WDB4632722X224015
40	WDB4632722X225378
41	WDB4632722X226481
42	WDB4632722X226762
43	WDB4632722X227910
44	WDB4632722X228038

45	WDB4632722X228236
46	WDB4632722X231462
47	WDB4632722X233760
48	WDB4632722X234070
49	WDB4632722X234911
50	WDB4632722X237735
51	WDB4632722X240896
52	WDB4632722X241383
53	WDB4632722X241656
54	WDB4632722X241955
55	WDB4632722X245323
56	WDB4632722X245902
57	WDB4632722X246901
58	WDB4632722X248367
59	WDB4632722X249609
60	WDB4632722X251513
61	WDB4632722X252964
62	WDB4632741X206006
63	WDB4633462X207231
64	WDB4633462X207493
65	WDB4633462X207559
66	WDB4633462X207762
67	WDB4633462X208089
68	WDB4633462X208512
69	WDB4633462X208568
70	WDB4633462X208623
71	WDB4633462X208668
72	WDB4633462X208742
73	WDB4633462X208830
74	WDB4633462X209367
75	WDB4633462X214494
76	WDB4633462X215397
77	WDB4633462X217768
78	WDB4633462X218088
79	WDB4633462X218118
80	WDB4633462X218618
81	WDB4633462X218919
82	WDB4633462X220082
83	WDB4633462X222143
84	WDB4633462X222420

85	WDB4633462X222505
86	WDB4633462X222630
87	WDB4633462X223759
88	WDB4633462X223804
89	WDB4633462X226304
90	WDB4633482X249686
91	WDB4633482X250117
92	WDB4633482X250916