

Recall Detail

| | |
|---|---|
| Ref No | 10000704 |
| Manufacturer | ISUZU |
| Vehicle Class | Commercial vehicle |
| Model/Type | ISUZU TF series |
| Dealer (phone no) | Triangle Motors Ltd (Tele: 2216 8163) |
| Subject | ISUZU E6 TF D-MAX Replace inlet camshaft and gear |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | Inlet camshaft gear may have micro crack due to improper production process. In the worst case. Micro crack on the gear will grow up and finally the teeth of the gear will be broken. As a result, the engine may be stalled during driving and will not restart. |
| Remedial Action | Replace the inlet camshaft and gear |
| Build Dates | 2017 |
| Launch Date | 22/06/2017 |
| Tentative Date of Recall Completion | 21/06/2022 |

TF series

| | | | | | |
|----|-------------------|----|-------------------|----|-------------------|
| 1 | MPATFS87JHT001480 | 11 | MPATFS87JHT003855 | 21 | MPATFS87JHT004297 |
| 2 | MPATFS87JHT001481 | 12 | MPATFS87JHT003854 | 22 | MPATFS87JHT004299 |
| 3 | MPATFR87JHT000051 | 13 | MPATFS87JHT003853 | 23 | MPATFS87JHT004291 |
| 4 | MPATFS87JHT001476 | 14 | MPATFS87JHT003852 | 24 | MPATFS87JHT004298 |
| 5 | MPATFS87JHT001483 | 15 | MPATFS87JHT003849 | 25 | MPATFS87JHT004295 |
| 6 | MPATFS87JHT001482 | 16 | MPATFS87JHT003856 | 26 | MPATFS87JHT004302 |
| 7 | MPATFS87JHT001475 | 17 | MPATFS87JHT003857 | 27 | MPATFS87JHT004288 |
| 8 | MPATFS87JHT003850 | 18 | MPATFS87JHT004423 | 28 | MPATFS87JHT004293 |
| 9 | MPATFS87JHT002683 | 19 | MPATFS87JHT004292 | | |
| 10 | MPATFS87JHT003851 | 20 | MPATFS87JHT004296 | | |