

Recall Detail	
Ref No	10000707
Manufacturer	Automobiles Peugeot
Vehicle Class	Private Car
Model/Type	308
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	Check the position of the electric lug-wiring harness assembly on the starter.
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The position of the starter wiring harness lug may not have been correctly fitted. Contact with a nearby metal part might cause a short circuit.
Remedial Action	Checking the fitting of the starter wiring harness lug and re-position it if necessary.
Build Dates	01/07/2015 – 30/04/2017
Launch Date	03/07/2017
Tentative Date of Recall Completion	31/12/2018

1	VF3LHAHXWFS328743
2	VF3LHAHXWGS197269
3	VF3LHAHXWGS197270
4	VF3LHAHXWGS197271
5	VF3LHAHXWGS197272
6	VF3LJAHXWFS350602
7	VF3LJAHXWGS202496
8	VF3LJAHXWGS202497
9	VF3LJAHXWGS202498
10	VF3LJAHXWGS202499
11	VF3LJAHXWGS236793
12	VF3LJAHXWGS236794
13	VF3LJAHXWGS249237
14	VF3LJAHXWGS249238
15	VF3LJAHXWGS263917
16	VF3LJAHXWGS265965
17	VF3LJAHXWGS265966
18	VF3LJAHXWGS267502
19	VF3LJAHXWGS267503
20	VF3LJAHXWGS270452
21	VF3LJAHXWGS270453

22	VF3LJAHXWGS270454
23	VF3LJAHXWGS270455
24	VF3LJAHXWGS271405
25	VF3LJAHXWHS018836
26	VF3LJAHXWHS018837
27	VF3LJAHXWHS018838
28	VF3LJAHXWHS018839
29	VF3LJAHXWHS020420
30	VF3LJAHXWHS023587
31	VF3LJAHXWHS023588
32	VF3LJAHXWHS027666
33	
34	
35	
36	
37	
38	
39	
40	