

Recall Detail

Ref No	10000711
Manufacturer	ASTON MARTIN
Vehicle Class	PRIVATE CAR
Model/Type	DB11
Dealer (phone no)	MF Jebsen Automotive Limited (2234 0562)
Subject	Incorrect Configuration of TPMS
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Incorrect coding installed in the Tyre Pressure Monitoring System (TPMS). This means that if the pressures in the tyres of the vehicle reduce because of a leak or puncture, the TPMS system will not give a warning to the driver at the required minimum tyre pressure.
Remedial Action	We will update the coding for the Tyre Pressure Monitor (TPM) module.
Build Dates	Manufactured from Oct 2016 – Jun 2017
Launch Date	14 July 2017
Tentative Date of Recall Completion	April 2018

1	SCFRLFAV1HGL00484
2	SCFRLFAV0HGL00492
3	SCFRLFAV6HGL00500
4	SCFRLFAV6HGL00626
5	SCFRLFAV2HGL00865
6	SCFRLFAV6HGL00898
7	SCFRLFAV6HGL00903
8	SCFRLFAV8HGL01406
9	SCFRLFAV5HGL01413
10	SCFRLFAV0HGL01416
11	SCFRLFAV0HGL01450
12	SCFRLFAV1HGL01473
13	SCFRLFAVXHGL01603
14	SCFRLFAV7HGL01669
15	SCFRLFAV8HGL02426
16	SCFRLFAV2HGL02521
17	SCFRLFAVXHGL02573
18	SCFRLFAV0HGL02601
19	

20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	