

## Recall Detail

<b>Ref No</b>	<b>10000752</b>
<b>Manufacturer</b>	INFINITI
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Q30 (H15)
<b>Dealer (phone no)</b>	Honest Motors Ltd. (Tel: 221682228)
<b>Subject</b>	Modify Driver Airbag Circuit
<b>Progress</b>	Running
<b>Affected Vehicle Identification Number (VIN)</b>	List as below
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>Infiniti has identified that due to an insufficiently robust design, the steering column has no electrical connection to ground other than the spiral cable. The airbag warning light will illuminate when spiral cable is damage. If the customer ignores the warning light and continues to drive for extended periods, electrostatic charge may build up on the steering wheel which under very limited circumstances could be discharged through the electrical circuit of the driver airbag.</p> <p>In an extreme case this discharge could be sufficient to trigger an unintended deployment of the driver airbag.</p>
<b>Remedial Action</b>	Modify Driver Airbag Circuit
<b>Build Dates</b>	2016 - 2017
<b>Launch Date</b>	05/02/2018
<b>Tentative Date of Recall Completion</b>	05/02/2021

Q30 (H15)

1.	SJKDCAH15U1011969	45.	SJKDCAH15U1050939
2.	SJKDCAH15U1012097	46.	SJKDCAH15U1051072
3.	SJKDCAH15U1013550	47.	SJKDCAH15U1051174
4.	SJKDCAH15U1013697	48.	SJKDCAH15U1051252
5.	SJKDCAH15U1016991	49.	SJKDCAH15U1051279
6.	SJKDCAH15U1017065	50.	SJKDCAH15U1051393
7.	SJKDCAH15U1017164	51.	SJKDCAH15U1051596
8.	SJKDCAH15U1017172	52.	SJKDCNH15U1002461
9.	SJKDCAH15U1017229	53.	SJKDCNH15U1002698
10.	SJKDCAH15U1017231	54.	SJKDCNH15U1002711
11.	SJKDCAH15U1017442	55.	SJKDCNH15U1002866
12.	SJKDCAH15U1017483	56.	SJKDCNH15U1003775
13.	SJKDCAH15U1017489	57.	SJKDCNH15U1003899
14.	SJKDCAH15U1017491	58.	SJKDCNH15U1004016
15.	SJKDCAH15U1017495	59.	SJKDCNH15U1004090
16.	SJKDCAH15U1018130	60.	SJKDCNH15U1004151
17.	SJKDCAH15U1018642	61.	SJKDCNH15U1004196
18.	SJKDCAH15U1018764	62.	SJKDCNH15U1004293
19.	SJKDCAH15U1019549	63.	SJKDCNH15U1004590
20.	SJKDCAH15U1020113	64.	SJKDCNH15U1004646
21.	SJKDCAH15U1045940	65.	SJKDCNH15U1004718
22.	SJKDCAH15U1046029	66.	SJKDCNH15U1004770
23.	SJKDCAH15U1046660	67.	SJKDCNH15U1004876
24.	SJKDCAH15U1046824	68.	SJKDCNH15U1004909
25.	SJKDCAH15U1046865	69.	SJKDCNH15U1005002
26.	SJKDCAH15U1047227	70.	SJKDCNH15U1005146
27.	SJKDCAH15U1047336	71.	SJKDCNH15U1005153
28.	SJKDCAH15U1047480	72.	SJKDCNH15U1005433
29.	SJKDCAH15U1047703	73.	SJKDCNH15U1005469
30.	SJKDCAH15U1048129	74.	SJKDCNH15U1005562
31.	SJKDCAH15U1048273	75.	SJKDCNH15U1005646
32.	SJKDCAH15U1048969	76.	SJKDCNH15U1005672
33.	SJKDCAH15U1049049	77.	SJKDCNH15U1005854
34.	SJKDCAH15U1049293	78.	SJKDCNH15U1012123
35.	SJKDCAH15U1049389	79.	SJKDDAH15U1009560
36.	SJKDCAH15U1049820	80.	SJKDDAH15U1009823
37.	SJKDCAH15U1049899	81.	SJKDDAH15U1016136
38.	SJKDCAH15U1050176	82.	SJKDDAH15U1016267
39.	SJKDCAH15U1050259	83.	SJKDDAH15U1016469

40.	SJKCAH15U1050383	84.	SJKDDAH15U1016779
41.	SJKCAH15U1050464	85.	SJKDDAH15U1016947
42.	SJKCAH15U1050669	86.	SJKDDAH15U1018539
43.	SJKCAH15U1050775	87.	SJKDDAH15U1018804
44.	SJKCAH15U1050826	88.	SJKDDAH15U1019724