

Recall Detail	
Ref No	10000776
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	M5 (F90)
Dealer (phone no)	31936688
Subject	Programming control units (electric fuel pump)
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	The fuel pressure drops in certain driving situations due to the electric fuel pump failing to deliver fuel. The engine may stop while driving.
Remedial Action	Program and code the control units
Build Dates	21.08.2017 - 18.04.2018
Launch Date	22/05/2018
Tentative Date of Recall Completion	30/11/2018

1	GA02718
2	GA02719
3	GA02734
4	GA02741
5	GA02748
6	GA02758
7	GA02759
8	GA02761
9	GA02762
10	GA02765
11	GA02816
12	GA02937
13	GA02939
14	GA02956
15	GA02965
16	GA02973
17	GA02974
18	GA03002
19	GA03003
20	GA03009
21	GA03010
22	GA03011

23	GA03017
24	GA03057
25	GA03058
26	GA03097
27	GA03098
28	GA03104
29	GA03105
30	GA03140