

Recall Detail	
Ref No	10000783
Manufacturer	BMW
Vehicle Class	Motor Cycle
Model/Type	G 310 R, G 310 GS
Dealer (phone no)	31936688
Subject	Retrofitting the bearing support for the side stand
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	The side stand connection can bend, or in an extreme case even break. The side stand becoming unsafe cannot be ruled out in the case that this fault should occur.
Remedial Action	The side stand connection will be checked for preliminary damage and an additional reinforcement will be installed.
Build Dates	Up to 02.05.2018
Launch Date	22/06/2018
Tentative Date of Recall Completion	31/12/2018

1	R802006
2	R802007
3	R807194
4	R807197
5	R807198
6	R810380
7	R810381
8	R834058
9	R839036
10	R840731
11	R840740
12	R841683
13	R843974
14	R843975
15	R843981