

Recall Detail

Ref No	10000811
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	ML-Class, GLE-Class, GL-Class & GLS-Class / 166 & 292
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Quarry Bay Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Replace oil dipstick of ACTIVE CURVE SYSTEM reservoir (4694531)
Progress	Running
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.
Description of Defect, how it came to light, and possible consequences if ignored.	Small quantities of hydraulic fluid could escape from the ACTIVE CURVE SYSTEM oil reservoir in affected vehicles. In the event of contact with hot component parts, a fire hazard cannot be ruled out.
Remedial Action	Replace the oil dipstick of the reservoir in affected vehicles as a precautionary measure.
Build Dates	ML-Class: 13/02/2012 - 31/05/2015 GLE-Class: 11/06/2015 - 12/04/2016 GL-Class: 12/04/2013 - 13/11/2015 GLS-Class: 01/02/2016 - 27/02/2016
Launch Date	26/07/2018
Tentative Date of Recall Completion	31/12/2018

1	WDC1660572A045535
2	WDC1660572A165625

3	WDC1660572A247750
4	WDC1660572A250380

5	WDC1660572A280686
6	WDC1660572A381079
7	WDC1660731A263386
8	WDC1660731A369185
9	WDC1660732A040866
10	WDC1660732A041239
11	WDC1660732A053000
12	WDC1660732A055016
13	WDC1660732A099950
14	WDC1660732A101374
15	WDC1660732A127785
16	WDC1660732A129485
17	WDC1660732A129586
18	WDC1660732A129961
19	WDC1660732A131019
20	WDC1660732A131092
21	WDC1660732A132161
22	WDC1660732A132218
23	WDC1660732A133607
24	WDC1660732A144042
25	WDC1660732A157637
26	WDC1660732A174579
27	WDC1660732A185810
28	WDC1660732A216271
29	WDC1660732A360458
30	WDC1660732A367191
31	WDC1660732A462238
32	WDC1660732A473310
33	WDC1660732A473792
34	WDC1660732A541252
35	WDC1660732A591551
36	WDC1660741A114973
37	WDC1660742A045668
38	WDC1660742A056299
39	WDC1660742A131485
40	WDC1660742A134133
41	WDC1660742A158270
42	WDC1660742A160366
43	WDC1660742A177964
44	WDC1660742A178693

45	WDC1660742A191042
46	WDC1660742A191525
47	WDC1660742A191588
48	WDC1660742A192328
49	WDC1660742A192387
50	WDC1660742A239336
51	WDC1660742A374191
52	WDC1660742A374614
53	WDC1660742A374771
54	WDC1660742A375449
55	WDC1660742A604614
56	WDC1660742A672227
57	WDC1660742A680134
58	WDC1660742A690797
59	WDC1668731A365170
60	WDC1668731A379442
61	WDC1668732A277682
62	WDC1668732A314800
63	WDC1668732A321567
64	WDC1668732A355171
65	WDC1668732A364345
66	WDC1668732A385387
67	WDC1668732A479914
68	WDC1668732A510228
69	WDC1668732A553596
70	WDC1668732A573350
71	WDC1668732A669518
72	WDC1668732A691206
73	WDC1668741A389753
74	WDC1668742A210505
75	WDC1668742A215721
76	WDC1668742A227312
77	WDC1668742A313984
78	WDC1668742A317438
79	WDC1668742A405177
80	WDC1668742A408843
81	WDC1668742A411280
82	WDC1668742A432449
83	WDC1668742A501331
84	WDC1668742A545849

85	WDC1668742A546076
86	WDC1668742A559026
87	WDC1668752A691207
88	WDC2923642A002360
89	WDC2923642A002888
90	WDC2923642A003079
91	WDC2923642A004854
92	WDC2923642A005286
93	WDC2923742A001080
94	WDC2923742A001362
95	WDC2923742A020816
96	WDC2923742A022078
97	WDC2923742A022122
98	WDC2923742A022228
99	WDC2923742A023487
100	WDC2923742A023676
101	WDC2923742A024608
102	WDC2923742A027540
103	WDC2923742A032517