

Recall Detail

| | |
|---|--|
| Ref No | 10000813 |
| Manufacturer | Daimler AG |
| Vehicle Class | Private car |
| Model/Type | GLC / 253 |
| Dealer (phone no) | Chai Wan Service Centre: 2504 6140 Quarry Bay Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140 |
| Subject | Rework trim on right and left C-pillars (6891236) |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall. |
| Description of Defect, how it came to light, and possible consequences if ignored. | The belt buckle of the outer-rear seats may be drawn into the gap between the C-pillar trim and rear side paneling and cannot be taken out again without aids in affected vehicle. In this case, the seat belt is not available at the affected seat. |
| Remedial Action | Rework the trim on the left and right C-pillar as a precautionary measure in affected vehicles. |
| Build Dates | 21/03/2018 - 11/04/2018 |
| Launch Date | 15/10/2018 |
| Tentative Date of Recall Completion | 31/12/2018 |

| | | | |
|---|-------------------|----|-------------------|
| 1 | WDC2539462F443618 | 7 | WDC2539462F444992 |
| 2 | WDC2539462F443713 | 8 | WDC2539462F445006 |
| 3 | WDC2539462F443933 | 9 | WDC2539462F445057 |
| 4 | WDC2539462F444046 | 10 | WDC2539462F445244 |
| 5 | WDC2539462F444492 | 11 | WDC2539462F445554 |
| 6 | WDC2539462F444572 | 12 | WDC2539462F445706 |

| | |
|----|-------------------|
| 13 | WDC2539462F445708 |
| 14 | WDC2539462F445859 |
| 15 | WDC2539462F445869 |
| 16 | WDC2539462F445932 |
| 17 | WDC2539462F446041 |
| 18 | WDC2539462F446190 |
| 19 | WDC2539462F446540 |
| 20 | WDC2539462F446596 |
| 21 | WDC2539462F446779 |
| 22 | WDC2539462F446872 |
| 23 | WDC2539462F447142 |
| 24 | WDC2539462F447236 |
| 25 | WDC2539462F447732 |
| 26 | WDC2539462F448025 |
| 27 | WDC2539462F448057 |
| 28 | WDC2539462F448192 |
| 29 | WDC2539462F448312 |
| 30 | WDC2539462F448671 |
| 31 | WDC2539462F449049 |
| 32 | WDC2539462F449185 |
| 33 | WDC2539462F449383 |
| 34 | WDC2539462F449699 |
| 35 | WDC2539462F449750 |
| 36 | WDC2539462F449810 |
| 37 | WDC2539462F450000 |
| 38 | WDC2539462F450384 |
| 39 | WDC2539462F450525 |
| 40 | WDC2539462F450831 |
| 41 | WDC2539462F451256 |
| 42 | WDC2539462F451425 |
| 43 | WDC2539462F451568 |
| 44 | WDC2539462F452000 |
| 45 | WDC2539462F452012 |
| 46 | WDC2539462F452093 |
| 47 | WDC2539462F452132 |
| 48 | WDC2539462F452220 |
| 49 | WDC2539462F452559 |
| 50 | WDC2539462F453370 |
| 51 | WDC2539462F453796 |
| 52 | WDC2539492F446264 |

| | |
|----|-------------------|
| 53 | WDC2539492F449633 |
| 54 | WDC2539492F450688 |
| 55 | WDC2539492F451908 |
| 56 | WDC2539492F452127 |
| 57 | WDC2539642F445228 |
| 58 | WDC2539642F447290 |
| 59 | WDC2539642F448402 |
| 60 | WDC2539642F452911 |