

## Recall Detail

<b>Ref No</b>	<b>10000837</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	C-Class & GLC / 205 & 253
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Update Audio 20 control unit software (8295004)
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The Audio 20 control unit software in affected vehicles do not correspond to specifications. Incorrect signal processing might mean that the status of the front passenger airbags displayed in the center console is not indicated correctly. In this case, driver might not be informed correctly of the actual activation status of the front passenger airbags and, as a result, not react adequately to potentially incorrect seat occupancy recognition.</p> <p>This could increase the risk of injury for the front passenger in the event of an accident.</p>
<b>Remedial Action</b>	Update the Audio 20 control unit software in affected vehicles as a precautionary measure.
<b>Build Dates</b>	04/08/2017 - 08/10/2018
<b>Launch Date</b>	18/12/2018
<b>Tentative Date of Recall Completion</b>	31/12/2019

1	WDC2533642F359735
2	WDC2533642F360161

3	WDC2533642F360331
4	WDC2533642F407612

5	WDC2533642F411883
6	WDC2533642F414916
7	WDC2533642F454239
8	WDC2533642F454342
9	WDC2533642F455983
10	WDC2533642F491456
11	WDC2533642F492182
12	WDC2533642F492298
13	WDC2533642F496328
14	WDC2533642F505552
15	WDC2533642F510807
16	WDC2533642F513505
17	WDC2533642F519389
18	WDC2533642F521228
19	WDC2533642F527143
20	WDC2533642F546517
21	WDC2539641F405803
22	WDC2539642F345201
23	WDC2539642F345388
24	WDC2539642F392417
25	WDC2539642F392570
26	WDC2539642F392910
27	WDC2539642F407954
28	WDC2539642F433763
29	WDC2539642F434823
30	WDC2539642F435408
31	WDC2539642F439188
32	WDC2539642F447290
33	WDC2539642F448402
34	WDC2539642F452911
35	WDC2539642F454446
36	WDC2539642F454643
37	WDC2539642F455387
38	WDC2539642F484258
39	WDC2539642F484305
40	WDC2539642F484651
41	WDC2539642F490227
42	WDC2539642F492892
43	WDC2539642F493895
44	WDC2539642F494709

45	WDC2539642F496616
46	WDC2539642F498588
47	WDC2539642F513363
48	WDC2539642F513949
49	WDC2539642F515363
50	WDC2539642F518024
51	WDC2539642F534962
52	WDC2539642F542846
53	WDC2539642F546727
54	WDD2050642R337684
55	WDD2050642R339167
56	WDD2050642R341556
57	WDD2050642R341758
58	WDD2050642R341789
59	WDD2050642R376730
60	WDD2050642R397378
61	WDD2050642R397464
62	WDD2052642F628325
63	WDD2052642F672745
64	WDD2053642F678893
65	WDD2053642F692011
66	WDD2053642F695120
67	WDD2053642F698698
68	WDD2053642F705074
69	WDD2053642F708483
70	WDD2053642F717095
71	WDD2053642F750785
72	WDD2054642F632485
73	WDD2054642F715210