| Recall Detail | |
|--|---|
| Ref No | 10000839 |
| Manufacturer | AUDI |
| Vehicle Class | Private Car |
| Model/Type | A3 (8V) |
| Dealer (phone no) | Premium Motors Ltd (3465 0000) |
| Subject | Servicing backrest |
| Progress | Running |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | On Audi A3 vehicles manufactured within a specific period, a rear seat backrest may be fitted on which the mounting for the head restraint is not correctly welded to the outer backrest frame for the rear seat. The support and protection functions of the head restraint may be restricted in the event of an accident. We expect that less than one percent of the vehicles will require a replacement backrest. |
| Remedial Action | The backrest on the rear seat bench must be checked on the affected vehicles and, if necessary, replaced. |
| Build Dates | Model Year: 2018 |
| Launch Date | 21 Dec 2018 |
| Tentative Date of Recall Completion | 21 Dec 2019 |

| 1 | WAUZZZ8V5JA132469 |
|---|-------------------|
| 2 | WAUZZZ8V2JA133658 |
| 3 | WAUZZZ8V8JA134765 |
| 4 | WAUZZZ8V1J1092486 |
| 5 | WAUZZZ8V9J1092512 |
| 6 | WAUZZZ8VXJ1094379 |
| 7 | WUAZZZ8V4J1908287 |
| 8 | WUAZZZ8V9J1908818 |
| | |