

Recall Detail	
Ref No	10000846
Manufacturer	BMW
Vehicle Class	Passenger Car
Model/Type	M3 and M4 (F80 and F82)
Dealer (phone no)	31936688
Subject	Replace the CFRP propeller shaft
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below: (Last Seven Numbers)
Description of Defect, how it came to light, and possible consequences if ignored.	The sliding piece in three-hole flange is able to slip out, thus resulting in lack of power transmission.
Remedial Action	Replacing the CFRP propeller shaft
Build Dates	01.03.2016 - 30.09.2016
Launch Date	19/12/2018
Tentative Date of Recall Completion	31/12/2019

1	5G47497
2	5G47690
3	5G47812
4	5G47906
5	5G47912
6	5G47928
7	5G47950
8	K345758
9	K345759
10	K345764
11	K345773
12	K345920
13	K345928
14	K346011
15	K346223
16	K346232
17	K346250
18	K346251
19	K346265
20	K346318
21	K346332
22	K346347

23

K577781
