

Recall Detail

Ref No	10000860
Manufacturer	ISUZU
Vehicle Class	Commercial vehicle
Model/Type	ISUZU TF series
Dealer (phone no)	Triangle Motors Ltd (Tele: 2216 8163)
Subject	ISUZU TF Series Rear Leaf Spring Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Some of ISUZU TF series vehicles may have rear leaf spring cracking at eye bush during driving. Parking brake was applied unexpectedly because parking brake cable was pulled by unsupported rear axle case.
Remedial Action	Replace both sides of counter measured rear leaf spring assembly.
Build Dates	2017 – 2018
Launch Date	02 /05/2019
Tentative Date of Recall Completion	01/05/2024

TF series

- | | |
|---------------------|---------------------|
| 1 MPATFS87JJT004197 | 8 MPATFS87JJT004661 |
| 2 MPATFS87JJT004198 | 9 MPATFS87JJT004662 |
| 3 MPATFS87JJT004657 | |
| 4 MPATFS87JJT004658 | |
| 5 MPATFS87JJT004199 | |
| 6 MPATFS87JJT004659 | |
| 7 MPATFS87JJT004660 | |