

## Recall Detail

<b>Ref No</b>	<b>10000861</b>
<b>Manufacturer</b>	Ford
<b>Vehicle Class</b>	N1 – Light Goods Vehicle
<b>Model/Type</b>	Ranger
<b>Dealer (phone no)</b>	Venture Motors Limited 3768 4898
<b>Subject</b>	Front brake hose
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The front brake hoses may be prone to rupture and could fail under certain operating conditions. It could lead to a symptom such as loss of brake fluid, illumination of brake warning indicator, increase brake pedal travel and extended stopping distance.
<b>Remedial Action</b>	Replace both front brake hoses
<b>Build Dates</b>	18 September 2014 to 13 September 2018
<b>Launch Date</b>	4 June 2019
<b>Tentative Date of Recall Completion</b>	30 June 2021

1	AFAPXXMJ2PHA01277
2	AFAPXXMJ2PHA01287
3	AFAPXXMJ2PHB66917
4	AFAPXXMJ2PHB66926
5	AFAPXXMJ2PHB66967
6	AFAPXXMJ2PHB69688
7	AFAPXXMJ2PHB69696
8	AFAPXXMJ2PHB69831
9	AFAPXXMJ2PHB69839
10	AFAPXXMJ2PHE45015
11	AFAPXXMJ2PHP58424
12	AFAPXXMJ2PHP58446
13	AFAPXXMJ2PHP58515
14	AFAPXXMJ2PHP59149
15	AFAPXXMJ2PHP59153
16	AFAPXXMJ2PHP60934
17	AFAPXXMJ2PHR77223
18	AFAPXXMJ2PHR77239
19	AFAPXXMJ2PHR79401

20	AFAPXXMJ2PHR79402
21	AFAPXXMJ2PHR79403
22	AFAPXXMJ2PHR79404
23	AFAPXXMJ2PHR80642
24	AFAPXXMJ2PHR80656
25	AFAPXXMJ2PHR80673
26	AFAPXXMJ2PHR80854
27	AFAPXXMJ2PHR81049
28	AFAPXXMJ2PHR81070
29	AFAPXXMJ2PHR81190
30	AFAPXXMJ2PJM18086
31	AFAPXXMJ2PJM18087
32	AFAPXXMJ2PJS66667
33	AFAPXXMJ2PJS66668
34	AFAPXXMJ2PJS66669
35	AFAPXXMJ2PJS66670
36	AFAPXXMJ2PJS66672
37	AFAPXXMJ2PJS66676
38	AFAPXXMJ2PJT72085

39	AFAPXXMJ2PJT73474
40	AFAPXXMJ2PJU04369
41	AFAPXXMJ2PJU05638
42	AFAPXXMJ2PJY51986
43	AFAPXXMJ2PJY52011
44	AFAPXXMJ2PJY52016
45	AFAPXXMJ2PJY56349
46	AFAPXXMJ2PJY56374
47	AFAPXXMJ2PJY56531
48	MNBUMFF50GW604911