

Recall Detail

Ref No	10000869
Manufacturer	AUDI
Vehicle Class	Private Car
Model/Type	Q5 (FY)
Dealer (phone no)	Premium Motors Ltd (3465 0000)
Subject	Securing wheel arch covers on Audi Q5
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	On Audi Q5 vehicles manufactured within a specific period it is possible that the latching connection on the wheel housing liner may fail. As a result, the wheel arch cover may come loose and, in the worst case, become detached from the vehicle.
Remedial Action	The wheel arch covers on the affected vehicles must be fixed in place.
Build Dates	Model Year: 2017 - 2019
Launch Date	5 Aug 2019
Tentative Date of Recall Completion	5 Aug 2020

1

WAUZZZFY2H2026241

2

WAUZZZFY9H2026785

3

WAUZZZFY6H2030499

4

WAUZZZFY9H2030710