

Recall Detail

Ref No	10000889
Manufacturer	Toyota
Vehicle Class	Taxi
Model/Type	Comfort HV
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Brake booster pump
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The brake booster pump may have been manufactured improperly, it may stop operating. If the brake booster pump stops operating, multiple warning lights and messages could illuminate, and/or audible chimes could sound. In this condition, braking assist could be lost completely after several brake pedal applications. A sudden and complete loss of braking assist while driving could increase the vehicle stopping distance and may increase the risk of a crash.
Remedial Action	Inspect and, if necessary, replace the brake booster pump
Build Dates	May 2019
Launch Date	November 2019
Tentative Date of Recall Completion	December 2020

1	JTNKC4B1209000523
2	JTNKC4B1209000537
3	JTNKC4B1709000520
4	JTNKC4B1709000534
5	JTNKC4B1909000518
6	JTNKC4B1909000521
7	JTNKC4B1909000485
8	JTNKC4B1009000486
9	JTNKC4B1009000505
10	JTNKC4B1109000500
11	JTNKC4B1309000532
12	JTNKC4B1409000488
13	JTNKC4B1609000489
14	JTNKC4B1609000492
15	JTNKC4B1709000484
16	JTNKC4B1709000503
17	JTNKC4B1909000499
18	JTNKC4B1909000504
19	JTNKC4B1X09000527
20	JTNKC4B1709000498
21	JTNKC4B1309000496

22	JTNKC4B1X09000494
23	JTNKC4B1509000502
24	JTNKC4B1209000487
25	JTNKC4B1209000490
26	JTNKC4B1009000536
27	JTNKC4B1109000531
28	JTNKC4B1209000540
29	JTNKC4B1409000538
30	JTNKC4B1909000535
31	JTNKC4B1X09000530
32	JTNKC4B1509000497
33	JTNKC4B1709000517
34	JTNKC4B1609000511