

Recall Detail

Ref No	10000890
Manufacturer	Lexus
Vehicle Class	Private Car
Model/Type	ES300h/UX250h
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4922)
Subject	Brake booster pump
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The brake booster pump may have been manufactured improperly, it may stop operating. If the brake booster pump stops operating, multiple warning lights and messages could illuminate, and/or audible chimes could sound. In this condition, braking assist could be lost completely after several brake pedal applications. A sudden and complete loss of braking assist while driving could increase the vehicle stopping distance and may increase the risk of a crash.
Remedial Action	Inspect and, if necessary, replace the brake booster pump
Build Dates	May 2019
Launch Date	November 2019
Tentative Date of Recall Completion	December 2020

1	JTHB21B1002052536
2	JTHB21B1902052311
3	JTHY65BH802020629
4	JTHY65BH802020808