

## Recall Detail

<b>Ref No</b>	<b>10000893</b>
<b>Manufacturer</b>	Nissan
<b>Vehicle Class</b>	Light Goods Vehicle
<b>Model/Type</b>	NV350 URVAN (E26)
<b>Dealer (phone no)</b>	Honest Motors Ltd. (Tel: 2216 8228)
<b>Subject</b>	Alternator and Drive Belt Replacement
<b>Progress</b>	Running
<b>Affected Vehicle Identification Number (VIN)</b>	List as below
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The tension of the drive belt could increase transiently due to a seized one-way clutch on the alternator. The bracket of the power steering pump driven by the same drive belt could become broken by fatigue caused by the belt tension.</p> <p>As a result, the power steering assistance is lost and steering will be heavy.</p>
<b>Remedial Action</b>	Alternator and Drive Belt Replacement
<b>Build Dates</b>	2013 - 2016
<b>Launch Date</b>	21/11/2019
<b>Tentative Date of Recall Completion</b>	21/11/2029

### NV350 URVAN (E26)

<b>1</b>	VR2E26-006750	<b>54</b>	VR2E26-032331	<b>107</b>	VR2E26-034900
<b>2</b>	VR2E26-009212	<b>55</b>	VR2E26-032440	<b>108</b>	VR2E26-034905
<b>3</b>	VR2E26-013925	<b>56</b>	VR2E26-033953	<b>109</b>	VR2E26-034912
<b>4</b>	VR2E26-015152	<b>57</b>	VR2E26-033982	<b>110</b>	VR2E26-034913
<b>5</b>	VR2E26-017057	<b>58</b>	VR2E26-033983	<b>111</b>	VR2E26-034914
<b>6</b>	VR2E26-025248	<b>59</b>	VR2E26-033985	<b>112</b>	VR2E26-034921
<b>7</b>	VR2E26-025352	<b>60</b>	VR2E26-034009	<b>113</b>	VR2E26-034925
<b>8</b>	VR2E26-026711	<b>61</b>	VR2E26-034022	<b>114</b>	VR2E26-034927
<b>9</b>	VR2E26-026718	<b>62</b>	VR2E26-034026	<b>115</b>	VR2E26-035221
<b>10</b>	VR2E26-026721	<b>63</b>	VR2E26-034033	<b>116</b>	VR2E26-035224
<b>11</b>	VR2E26-026725	<b>64</b>	VR2E26-034050	<b>117</b>	VR2E26-035225
<b>12</b>	VR2E26-026733	<b>65</b>	VR2E26-034065	<b>118</b>	VR2E26-035232
<b>13</b>	VR2E26-026736	<b>66</b>	VR2E26-034098	<b>119</b>	VR2E26-035236
<b>14</b>	VR2E26-026750	<b>67</b>	VR2E26-034107	<b>120</b>	VR2E26-035238
<b>15</b>	VR2E26-026755	<b>68</b>	VR2E26-034117	<b>121</b>	VR2E26-035251
<b>16</b>	VR2E26-026764	<b>69</b>	VR2E26-034118	<b>122</b>	VR2E26-035252
<b>17</b>	VR2E26-026765	<b>70</b>	VR2E26-034121	<b>123</b>	VR2E26-035255
<b>18</b>	VR2E26-026766	<b>71</b>	VR2E26-034132	<b>124</b>	VR2E26-035258
<b>19</b>	VR2E26-026768	<b>72</b>	VR2E26-034142	<b>125</b>	VR2E26-035265
<b>20</b>	VR2E26-026770	<b>73</b>	VR2E26-034143	<b>126</b>	VR2E26-035266
<b>21</b>	VR2E26-026778	<b>74</b>	VR2E26-034159	<b>127</b>	VR2E26-035276
<b>22</b>	VR2E26-026788	<b>75</b>	VR2E26-034169	<b>128</b>	VR2E26-035279
<b>23</b>	VR2E26-026789	<b>76</b>	VR2E26-034184	<b>129</b>	VR2E26-035281
<b>24</b>	VR2E26-026792	<b>77</b>	VR2E26-034194	<b>130</b>	VR2E26-035287
<b>25</b>	VR2E26-026795	<b>78</b>	VR2E26-034208	<b>131</b>	VR2E26-035290
<b>26</b>	VR2E26-026801	<b>79</b>	VR2E26-034216	<b>132</b>	VR2E26-035291
<b>27</b>	VR2E26-026806	<b>80</b>	VR2E26-034219	<b>133</b>	VR2E26-035300
<b>28</b>	VR2E26-026807	<b>81</b>	VR2E26-034797	<b>134</b>	VR2E26-035309
<b>29</b>	VR2E26-026809	<b>82</b>	VR2E26-034810	<b>135</b>	VR2E26-035323
<b>30</b>	VR2E26-026812	<b>83</b>	VR2E26-034811	<b>136</b>	VR2E26-035325
<b>31</b>	VR2E26-026818	<b>84</b>	VR2E26-034812	<b>137</b>	VR2E26-035330
<b>32</b>	VR2E26-026834	<b>85</b>	VR2E26-034813	<b>138</b>	VR2E26-035331
<b>33</b>	VR2E26-026835	<b>86</b>	VR2E26-034814	<b>139</b>	VR2E26-035794
<b>34</b>	VR2E26-026845	<b>87</b>	VR2E26-034821	<b>140</b>	VR2E26-035822
<b>35</b>	VR2E26-026850	<b>88</b>	VR2E26-034823	<b>141</b>	VR2E26-035823
<b>36</b>	VR2E26-026852	<b>89</b>	VR2E26-034826	<b>142</b>	VR2E26-035836
<b>37</b>	VR2E26-026861	<b>90</b>	VR2E26-034838	<b>143</b>	VR2E26-035870
<b>38</b>	VR2E26-026868	<b>91</b>	VR2E26-034839	<b>144</b>	VR2E26-035875
<b>39</b>	VR2E26-026869	<b>92</b>	VR2E26-034841	<b>145</b>	VR2E26-035879
<b>40</b>	VR2E26-026875	<b>93</b>	VR2E26-034844	<b>146</b>	VR2E26-035892

<b>41</b>	VR2E26-026881	<b>94</b>	VR2E26-034847	<b>147</b>	VR2E26-035900
<b>42</b>	VR2E26-026888	<b>95</b>	VR2E26-034857	<b>148</b>	VR2E26-035921
<b>43</b>	VR2E26-026889	<b>96</b>	VR2E26-034863	<b>149</b>	VR2E26-035945
<b>44</b>	VR2E26-026891	<b>97</b>	VR2E26-034865	<b>150</b>	VR2E26-035955
<b>45</b>	VR2E26-029205	<b>98</b>	VR2E26-034868	<b>151</b>	VR2E26-035956
<b>46</b>	VR2E26-029232	<b>99</b>	VR2E26-034870	<b>152</b>	VR2E26-035982
<b>47</b>	VR2E26-029252	<b>100</b>	VR2E26-034871	<b>153</b>	VR2E26-036011
<b>48</b>	VR2E26-029253	<b>101</b>	VR2E26-034874	<b>154</b>	VR2E26-036013
<b>49</b>	VR2E26-029265	<b>102</b>	VR2E26-034888	<b>155</b>	VR2E26-036036
<b>50</b>	VR2E26-029270	<b>103</b>	VR2E26-034890	<b>156</b>	VR2E26-036037
<b>51</b>	VR2E26-029290	<b>104</b>	VR2E26-034893	<b>157</b>	VR2E26-036046
<b>52</b>	VR2E26-029294	<b>105</b>	VR2E26-034897		
<b>53</b>	VR2E26-032200	<b>106</b>	VR2E26-034899		