

Recall Detail

Ref No	10000895
Manufacturer	Subaru
Vehicle Class	Private Car
Model/Type	SUBARU Legacy
Dealer (phone no)	Motor Image Kowloon Limited (23936118)
Subject	Luminescent meter overheating
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	Due to inappropriate circuit structure on the luminescent meter, if the cabin is exposed to moisture for a long time, power line of the circuit board may cause an electrical short, leading the circuit board to overheat.
Remedial Action	Replace the fuse at meter's circuit board
Build Dates	1999-2001
Launch Date	4 th April 2019
Tentative Date of Recall Completion	31 st December 2021

1	BE5-011779
2	BE5-011781
3	BE5-011785
4	BE5-011788
5	BE5-011797
6	BE5-011818
7	BE5-011823
8	BE5-011862
9	BE5-011872
10	BE5-011873
11	BE5-011889
12	BE5-011982
13	BE5-037638
14	BE5-037645
15	BE5-037657
16	BE5-037661
17	BE5-037696
18	BE5-037710
19	BE5-037712
20	BE5-037715
21	BH5-090581

22	BE5-063537
23	BE5-063626
24	BE5-063919
25	BE5-064105
26	BE5-064304
27	BE5-068260
28	BE5-068413
29	BE5-068426
30	BE5-068474
31	BE5-069309
32	BE5-069537
33	BE5-069545
34	BE5-069569
35	BE5-069626
36	BH5-114196
37	BH5-145602
38	BH5-145662
39	BE5-011776
40	BE5-011783
41	BE5-011786
42	BE5-011787

43	BE5-011789
44	BE5-011790
45	BE5-011795
46	BE5-011805
47	BE5-011842
48	BE5-011844
49	BE5-011864
50	BE5-011870
51	BE5-011876
52	BE5-011879
53	BE5-011880
54	BE5-011882
55	BE5-011886
56	BE5-011894
57	BE5-011895
58	BE5-011896
59	BE5-011905
60	BE5-011906
61	BE5-011915
62	BE5-011924
63	BE5-011929
64	BE5-011937
65	BE5-011960
66	BE5-011961
67	BE5-011979
68	BE5-011981
69	BE5-011984
70	BE5-011988
71	BE5-011990
72	BE5-037629
73	BE5-037634
74	BE5-037639
75	BE5-037640
76	BE5-037641
77	BE5-037649
78	BE5-037664
79	BE5-037673
80	BE5-037682
81	BE5-037689
82	BE5-037694

83	BE5-037703
84	BE5-037704
85	BE5-037705
86	BH5-090555
87	BH5-090591
88	BH5-090597
89	BH5-096147
90	BH5-096149
91	BH5-096173
92	BH5-096185
93	BE5-063487
94	BE5-063519
95	BE5-063660
96	BE5-063668
97	BE5-063769
98	BE5-063788
99	BE5-063915
100	BE5-064013
101	BE5-064123
102	BE5-064218
103	BE5-064229
104	BE5-064251
105	BE5-064302
106	BE5-068120
107	BE5-068152
108	BE5-068164
109	BE5-068345
110	BE5-068364
111	BE5-068411
112	BE5-068417
113	BE5-068493
114	BE5-068506
115	BE5-068562
116	BE5-069166
117	BE5-069184
118	BE5-069204
119	BE5-069263
120	BE5-069266
121	BE5-069293
122	BE5-069382

123	BE5-069434
124	BE5-069462
125	BE5-069519
126	BE5-069594
127	BE5-069602
128	BE5-080779
129	BE5-080826
130	BE5-080842
131	BE5-080901
132	BE5-080984
133	BE5-081014
134	BE5-081061
135	BE5-081703
136	BE5-081707
137	BE5-081711
138	BE5-081723
139	BH5-114178
140	BH5-114645
141	BH5-120806
142	BH5-120976
143	BH5-120996
144	BH5-121108
145	BH5-121277
146	BH5-145635
147	BH5-145789
148	BH5-121157
149	BE5-011775
150	BE5-011825
151	BE5-011885
152	BE5-037663
153	BE5-037667
154	BE5-037698
155	BH5-090551
156	BH5-096217
157	BE5-068302
158	BE5-068483
159	BE5-068565
160	BE5-069373
161	BE5-069444
162	BE5-069592

163	BE5-080791
164	BE5-080857
165	BH5-114037
166	BH5-120876
167	BH5-120891
168	BH5-120960
169	BH5-121307
170	BH5-145752
171	BE5-011772
172	BE5-063500
173	BE5-064237
174	BE5-068369
175	BE5-068535
176	BE5-081051
177	BH5-114423
178	BE5-011814
179	BE5-068174