

Recall Detail

Ref No	10000902
Manufacturer	Bentley
Vehicle Class	Private car
Model/Type	Supersport - Supersport Convertible - Continental 24
Dealer (phone no)	Ap Lei Chau Service Center Tel: 25537713 Tsuen Wan Service Center Tel: 21119679 Kowloon Bay Service Center Tel: 22621288
Subject	Supersport - Supersport Convertible - Continental 24 – Power Assist Steering Pipe Union Incorrect Dimensions
Progress	In process
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	It is possible for the PAS cooler hose to become detached from the stub pipe. This is due to the supplier manufacturing the part to an incorrect dimension. Should the hose detach, the vehicle will lose the hydraulic steering fluid, which could result in the loss of steering control. The hydraulic steering fluid leak increase the risk of a vehicle fire and of an accident to following traffic.
Remedial Action	PAS cooler stub pipes with correct fitting and dimensions to be installed.
Build Dates	Model Year: From 2016 to 2018
Launch Date	10 Dec 2019
Tentative Date of Recall Completion	10 Dec 2020

1	SCBFF63WXHC065575
2	SCBFF63W7HC065582
3	SCBFF63W0HC065648
4	SCBFF63W9HC065745