

Recall Detail

Ref No	10000913
Manufacturer	Mazda Motor Corporation
Vehicle Class	Private Car
Model/Type	Mazda3
Dealer (phone no)	Vang lek Motors (Hong Kong) Limited 3768 4848
Subject	Vehicle unexpectedly stop while driving
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	On certain vehicles, the inappropriate programming of the brake support control software may cause the vehicle to falsely detect an obstacle in front of the vehicle while driving which leads the vehicle may unexpectedly stop while driving. In the worst case, the unexpected brake would increase the risk of a rear-end crash from a following vehicle.
Remedial Action	Reprogram the brake support control program.
Build Dates	1 st April, 2019 to 19 th October, 2019
Launch Date	10/01/2020
Tentative Date of Recall Completion	10/01/2021

1	JM6BP2S7AK1102899
2	JM6BP2H7AK1103055
3	JM6BP2H7AK1103079
4	JM6BP2H7AL1103609
5	JM6BP2S7AL1103642
6	JM6BP2H7AL1103670
7	JM6BP2S7AL1103682
8	JM6BP2H7AL1103739
9	JM6BP2S7AL1103751
10	JM6BP2H7AL1103776
11	JM6BP2H7AL1103807
12	JM6BP2H7AL1103819
13	JM6BP2H7AL1103956
14	JM6BP2S7AL1103996
15	JM6BP2H7AL1104020