

Recall Detail

Ref No	10000916
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	RAV4
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Driver Front Airbag Inflator Replacement
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The subject vehicles are equipped with a single-stage non-azide front driver airbag inflator (Takata-designated NADI) as original equipment; these inflators do not contain phase stabilized ammonium nitrate (PSAN) propellant. Although not confirmed at this time by Toyota with regard to the subject vehicles, according to a Defect Information Report filed by Takata on November 26, 2019 (19E-080), the propellant in some of the involved inflators may absorb moisture over time, which Takata believes is related to the foil seal of the inflator. The absorption of moisture into the propellant over time could lead to slow deployment or inflator rupture in situations where the airbags are commanded to deploy. The potential for such abnormal deployment scenarios to occur may require or be exacerbated by other factors and variables beyond propellant moisture absorption and are not yet fully understood by Takata or Toyota. If an abnormal deployment of the driver airbag occurs, this could increase the risk of injury in the event of a crash. The likelihood of such an occurrence in the subject vehicles is unknown, but, out of an abundance of caution, Toyota is submitting this report.
Remedial Action	Replace the driver front airbag inflator
Build Dates	December 1997 to August 1999
Launch Date	February 2020
Tentative Date of Recall Completion	December 2021

1	JT171SC1000215265
2	JT172SC1100173116
3	JT172SC1100171287
4	JT171SC1000195891
5	JT172SC1100172702
6	JT171SC1000177388
7	JT171SC1000178954
8	JT171SC1000196103
9	JT171SC1000195023
10	JT172SC1100173233
11	JT172SC1107153085
12	JT171SC1000179185
13	JT172SC1100171996
14	JT172SC1100172502

15	JT172SC1100174645
16	JT172SC1100171911
17	JT171SC1000178486
18	JT172SC1107151877
19	JT172SC1100171719
20	JT172SC1100171941
21	JT172SC1100171758
22	JT171SC1000177222
23	JT172SC1100173104
24	JT171SC1000178680
25	JT172SC1107108369
26	JT172SC1100173069
27	JT171SC1000178647
28	JT171SC1000204784
29	JT172SC1100172372

30	JT171SC1000177301
31	JT172SC1100172975
32	JT172SC1107128776
33	JT171SC1000186082
34	JT172SC1100173164
35	JT172SC1100172764
36	JT171SC1000188981
37	JT171SC1000178467
38	JT171SC1000178534
39	JT171SC1000179533
40	JT171SC1000196005
41	JT171SC1000178734
42	JT171SC1000177511
43	JT171SC1000179373
44	JT171SC1000177353
45	JT172SC1100172895
46	JT172SC1100173176
47	JT172SC1100172932
48	JT171SC1000189026
49	JT171SC1000178960
50	JT171SC1000178626
51	JT171SC1000177157
52	JT171SC1000178810
53	JT171SC1000179229
54	JT171SC1000214793
55	JT172SC1100171432
56	JT172SC1107152780
57	JT171SC1000178041
58	JT171SC1000186481
59	JT172SC1100171013
60	JT172SC1100178172
61	JT171SC1000214886
62	JT171SC1000177751
63	JT172SC1100171299
64	JT172SC1100171474
65	JT172SC1100174260
66	JT171SC1000178580
67	JT171SC1000214580
68	JT172SC1107152133
69	JT171SC1000177664
70	JT171SC1000177847
71	JT171SC1000178392
72	JT171SC1000178759

73	JT171SC1000178798
74	JT171SC1000178863
75	JT171SC1000178905
76	JT171SC1000179009
77	JT171SC1000186447
78	JT171SC1000190559
79	JT171SC1000190661
80	JT171SC1000196173
81	JT172SC1100171624
82	JT172SC1100172126
83	JT172SC1100172383
84	JT172SC1100172826
85	JT172SC1100173034
86	JT172SC1107151595
87	JT172SC1107152261
88	JT172SC1107152901