

Recall Detail

Ref No	10000923
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	G 63 / 463
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Routing of door wiring harness (5491016)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The wiring harnesses of the front doors may have been unfavorably installed in affected vehicles. Individual cables may have been damaged due to the movement of the wiring harness during the opening and closing of the doors.</p> <p>Depending on the affected cable, different malfunctions may occur; incl. the restraint system may trigger in a delayed manner during a side impact, the position information during an emergency call may be incorrect or the door may not automatically unlock in the case of an accident.</p> <p>This would increase the risk of injury for the vehicle occupants in an accident.</p>
Remedial Action	As a precautionary measure in affected vehicles, change the routing of the wiring harness of the front doors or replace the wiring harness- in the case of damage.
Build Dates	07/09/2018 - 04/12/2018
Launch Date	14/02/2020
Tentative Date of Recall Completion	31/12/2020

1	WDB4632761X302417
2	WDB4632761X302478
3	WDB4632762X300658
4	WDB4632762X301013
5	WDB4632762X302531
6	WDB4632762X302540
7	WDB4632762X302571
8	WDB4632762X302577
9	WDB4632762X302597
10	WDB4632762X302676
11	WDB4632762X302794
12	WDB4632762X302924
13	WDB4632762X303030
14	WDB4632762X303103
15	WDB4632762X303196
16	WDB4632762X303207
17	WDB4632762X303286
18	WDB4632762X303386
19	WDB4632762X303450
20	WDB4632762X303487
21	WDB4632762X303543
22	WDB4632762X303626
23	WDB4632762X303644
24	WDB4632762X303906
25	WDB4632762X304037
26	WDB4632762X304260
27	WDB4632762X304487
28	WDB4632762X304581
29	WDB4632762X304587
30	WDB4632762X304754
31	WDB4632762X304882
32	WDB4632762X304986
33	WDB4632762X305001
34	WDB4632762X305085
35	WDB4632762X305233

36	WDB4632762X305236
37	WDB4632762X305461
38	WDB4632762X305488
39	WDB4632762X305497
40	WDB4632762X307051
41	WDB4632762X307135
42	WDB4632762X307839
43	WDB4632762X308383
44	WDB4632762X308539
45	WDB4632762X308691
46	WDB4632762X308753
47	WDB4632762X308788
48	WDB4632762X308811
49	WDB4632762X308875
50	WDB4632762X309029